

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
1630 Chestnut Street Tower II

May 30, 1985

BLRD-50-438/85-15
BLRD-50-439/85-15

U.S. Nuclear Regulatory Commission
Region II
Attn: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - INSPECTION OF HEATING, VENTILATING, AND
AIR-CONDITIONING DUCT SUPPORT - BLRD-50-438/85-15 AND BLRD-50-439/85-15 - FIRST
INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
A. Hardin on May 2, 1985 in accordance with 10 CFR 50.55(e) as
NCR BL-A-85-05-D-01. Enclosed is our first interim report. We expect to
submit our next report on or about August 31, 1985.

If you have any questions, please get in touch with R. H. Shell at
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Hufham
J. W. Hufham, Manager
Licensing and Regulations

Enclosure

cc: Mr. James Taylor, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center (Enclosure)
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8507160135 850530
PDR ADOCK 05000438
S PDR

ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2
INSPECTION OF HEATING, VENTILATING, AND AIR-CONDITIONING DUCT SUPPORTS
BLRD-50-438/85-15 AND BLRD-50-439/85-15
10 CFR 50.55(e)
NCR BL-A-85-05-D-01
FIRST INTERIM REPORT

Description of Deficiency

A quality assurance audit identified potential deficiencies in documenting the inspection of heating, ventilating, and air-conditioning (HVAC) duct supports. The audit team, through interviews and investigation, was unable to find conclusive evidence that required installation inspections of numerous insulated HVAC supports had been performed and documented and was unable to determine the quality status of the HVAC supports.

Interim Progress

TVA is evaluating the audit findings to determine what corrective actions are required. The Records Accountability Program is being reviewed to determine if deficiencies exist related to the documentation of HVAC duct support inspections. This review will be used to determine the nature and extent of the deficiencies.