



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

July 24, 1985

Docket No. 99900741/85-01

Power Conversion Products, Inc.  
ATTN: Mr. C. F. Seyer  
Executive Vice President  
42 East Street  
Post Office Box 380  
Crystal Lake, Illinois 60014

Gentlemen:

This refers to the inspection conducted by Mr. K. R. Naidu of this office on May 22-23, 1985, of your facilities located at Crystal Lake, Illinois, and to the discussions of our findings with you and your QA Manager at the conclusion of the inspection.

The purpose of this inspection was to review the implementation of your Quality Assurance Program and corrective action taken relative to 10 CFR Part 21 reports. Areas examined during the inspection and our findings are discussed in the enclosed report. Within these areas, the inspection consisted of an examination of procedures and representative records, interviews with personnel, and observations by the inspector.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

*James C. Stone*  
For Gary G. Zech, Chief  
Vendor Program Branch  
Division of Quality Assurance, Vendor  
and Technical Training Center Programs  
Office of Inspection and Enforcement

Enclosure:  
Appendix A - Inspection Report 99900741/85-01

8507290423 850724  
PDR GA999 EMVPOWER  
99900741 PDR

PROCESSING

Original document not available to NRC

Certified by *Sherry Meador*

IE09  
11

Power Conversion Products, Inc.

July 24, 1985

Distribution

DMB-IE:09

VPB Reading

DQAVT Reading

RVollmer

JTCollins


JStone


GHolahan, NRR


Region III


EMerschoff

KNaidu

  
VPB:DQAVT  
KNaidu:gmk  
7/1/85

  
EC/VPB:DQAVT  
EMerschoff  
8/3/85

  
For BC/VPB:DQAVT  
GZech  
9/19/85

  
DIR/DQAVT  
BKGrimes  
9/25/85