

Telecopy

Mr. J. P. O'Reilly, Director
 USNRC Region II
 Office of Inspection and Enforcement
 101 Marietta St., Suite 3100
 Atlanta, GA 30303

RE: Docket 50-302 License LPR-72

This will confirm a report made to Mr. Donald Price of your office at 1400, 2 July 1979, that at 1000 2 July 1979, it was determined that ninety-two (92) pipe supports have thus far been identified as inadequate based on the guidelines of I & E Bulletins 79-02 and 79-02 revision 1. This is reported under Technical Specification 6-9-1-81.

The affected supports are being redesigned and installed under modification 79-6-86. Three of the ninety-two supports (SWH-522, PCH-101, DHM-645), have a safety factor less than one (1) and have been identified as a constraint for startup.

Guy P. Beatty, Jr.
 Nuclear Plant Manager
 Crystal River Unit 3
 Florida Power Corporation

cc W. P. Stewart
 J. C. Hobbs
 D. R. Quick

J. P. O'REILLY
~~B. THOMPSON~~
 C. M. UPRIGHT
 P. D. CHENDEMI
 W. B. KENNA
 F. I. LONG
 B. E. MURPHY
 B. T. SUTHERLAND
 K. M. CLARK

Lewis
Jenkins
Quick

7908800775

A2

60

79 JUL 3 AIO: 27