

Docket No. 50-373
Docket No. 50-374

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

This refers to the meeting held on September 12, 1985, between Mr. W. D. Shafer and Mr. G. J. Diederich of our respective staffs. The intent of this meeting was to discuss the measures that LaSalle management has initiated as a result of the weaknesses identified earlier this year in the area of Radiological Controls (reference Inspection Reports 50-373/85014; 50-374/85014).

We appreciate your staff's prompt action to address these issues and want to encourage you to continue this positive performance. We will monitor these efforts in our future inspections. To assure ourselves that the corrective measures already in place will remain effective and that newly identified weaknesses will be promptly addressed by your staff, we intend to implement augmented inspections of your radiological controls and chemistry program commencing with the start of the first refueling outage to be conducted on LaSalle Unit 1 during the fall of this year.

We will discuss our increased inspection activities with your site personnel in the near future. If you desire any further information concerning this letter please contact Mr. L. R. Greger (312-790-5644) of my staff.

Sincerely,

8509270004 850920
PDR ADOCK 05000373
Q PDR

Jack A. Hind
Jack A. Hind, Director
Division of Radiation Safety
and Safeguards

cc: D. L. Farrar, Director
of Nuclear Licensing
G. J. Diederich, Plant
Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Phyllis Dunton, Attorney
General's Office, Environmental
Control Division

RIII *[Signature]*
Schumacher/as

RIII *[Signature]*
Greger

RIII *[Signature]*
Tambling
9/20

RIII *[Signature]*
Shafer
9/20

RIII *[Signature]*
Hind
9/20

IEOL 10/10
Test Delta RII