



UNITED STATES
NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

December 24, 1996

Mr. James J. O'Connor
Chairman and Chief Executive Officer
Commonwealth Edison Company
Post Office Box 767
Chicago, Illinois 60690

SUBJECT: INDEPENDENT SAFETY INSPECTION OF DRESDEN NUCLEAR POWER STATION
(NRC INSPECTION REPORT 50-237/96-201; 50-249/96-201)

Dear Mr. O'Connor:

I am forwarding the report on the Dresden Nuclear Power Station by the U.S. Nuclear Regulatory Commission's (NRC) Independent Safety Inspection (ISI) team. The purposes of the ISI were: to evaluate the effectiveness of your corrective action programs; to provide an independent assessment of conformance with the design and licensing bases; to evaluate the conduct and effectiveness of maintenance activities, including work processes, post-maintenance testing, and implementation of maintenance rule activities; and to provide an independent assessment of operational safety performance.

The ISI team was large and multi-disciplined in order to provide a thorough, in-depth review. The team, which consisted of 21 members, was managed by a senior NRC manager and included an observer from the state of Illinois. During the two onsite inspection periods, team members also conducted interviews at Commonwealth Edison's (ComEd's) corporate offices in Downers Grove and Chicago. To ensure an independent perspective, the NRC members were selected from NRC offices other than Region III. Additionally, only persons with no significant prior responsibility for regulating ComEd facilities were chosen, and the team manager reported to me.

The ISI was conducted in response to the NRC's concern about the long history of poor performance at Dresden Station. Dresden Station was first placed on the NRC Watch List as a Category 2 plant in 1987. Improved performance resulted in the site being removed from the Watch List in December 1988. Performance subsequently declined and in January 1992, Dresden Station was again placed on the NRC Watch List. For the past several years, safety performance has been cyclic with identified weaknesses in plant material condition, procedure quality and adherence, engineering and licensing support, work performance, communications, execution of management expectations, and supervision and control of work activities.

Improvements have been made in all the areas that were inspected. The rate of improvement has been incremental and has varied significantly among Dresden Station organizations. Safety performance has significantly improved in plant operations while the level of improvement in engineering has not yet resulted in fully effective problem identification and resolution as evidenced by the failure to identify significant weaknesses in design control and maintenance of design basis calculations, and the failure to resolve a number of long-

NRC FILE CENTER COPY

310038

9612270052 XA 12-31-96

IEOI 1/1

standing problems affecting safety-systems. The results of improvement initiatives in radiological protection, maintenance, testing, and self-assessment were mixed.

Notwithstanding these improvements, the ISI identified significant weaknesses in the areas of radiation protection, maintenance and testing, engineering, and in the implementation of the corrective action program. A number of significant deficiencies were identified during the inspection. Deficiencies are apparent failures to comply with a regulatory requirement or apparent failures to satisfy a written commitment that is not legally binding. A summary of these deficiencies is provided in Appendix F of the enclosed report, and many of them appear to be related to two root causes: until recently, corporate and site managers were not fully focused on correcting organizational, programmatic, process and material condition problems that have been evident for a number of years; and corporate oversight of and involvement with contractor engineering services firms were not sufficient to ensure the appropriate control and maintenance of design basis calculations.

Corrective actions to resolve the lack of control and maintenance of design basis calculations are only now being implemented after the problem was brought to the attention of Dresden Station senior managers by the ISI. Because of the significance of the engineering and design basis issues, ComEd, in a letter dated November 8, 1996, committed to a number of actions to provide further confidence in the adequacy of the design basis and engineering activities at Dresden Station. The short-term actions were confirmed by an NRC Confirmatory Action Letter, dated November 21, 1996.

The ISI also identified that significant challenges to continued improvement exist. First, the level of emergent work continues to hamper the ability to perform planned work consistently, which is preventing the reduction of the corrective maintenance backlog to the desired level and is unnecessarily challenging plant safety systems and plant operators. Second, corrective actions that have been implemented for programmatic and hardware problems have not been effective in a number of areas, resulting in repetitive problems. Finally, the full implications of the lack of design control and maintenance of design basis calculations have not yet been determined, pending ComEd's continuing reviews in this area.


The results of the ISI were presented during an exit meeting, open to public observation, on December 12, 1996, at Dresden Station. I request that following the review of this report, you determine the additional actions needed to ensure the long-term resolution of the deficiencies identified. NRC Region III will be responsible for followup of the issues identified during the inspection, including the assessment of corrective actions and the determination of any enforcement action that is deemed appropriate.

Mr. James J. O'Connor

- 3 -

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room. Should you have any questions concerning this inspection, I would be pleased to discuss them with you.

Sincerely,


James M. Taylor
Executive Director for Operations

Dockets: 50-237; 50-249

Enclosure:
NRC Inspection Report
50-237/96-201; 50-249/96-201
w/Appendices

cc w/enclosure:
See next page

Mr. James J. O'Connor

- 4 -

cc w/enclosure:

D. A. Sager, Vice President,
Generation Support
Commonwealth Edison Company
Executive Towers West III
1400 Opus Place, Suite 300
Downers Grove, IL 60515

H. W. Keiser, Chief Nuclear
Operations Officer
Commonwealth Edison Company
1400 Opus Place
Downers Grove, IL 60515

T. Neuman, Station Manager, Unit 1
Dresden Nuclear Power Station
6500 North Dresden Road
Morris, IL 60450

M. Heffley, Station Manager, Units 2 and 3
Dresden Nuclear Power Station
6500 North Dresden Road
Morris, IL 60450

F. Spangenberg, Regulatory Assurance
Manager
Regulatory Assurance Supervisor
Dresden Nuclear Power Station
6500 North Dresden Road
Morris, IL 60450

D. Farrar, Nuclear Regulatory
Services Manager
Commonwealth Edison Company
Executive Towers West III
1400 Opus Place, Suite 300
Downers Grove, IL 60515

Richard Hubbard
MHB Technical Associates
1723 Hamilton Avenue
Suite K
San Jose, CA 95125

Nathan Schloss, Economist
Office of the Attorney General
Public Utilities Division
100 West Randolph, 12th Floor
Chicago, IL 60601

Mr. James J. O'Connor

- 5 -

cc w/enclosure: (Continued)

State Liaison Officer
State of Illinois
1035 Outer Park Drive
Springfield, IL 62704

Chairman, Illinois Commerce Commission
Public Utility Commission
527 East Capitol Avenue
Springfield, IL 62706

Document Control Desk-Licensing
Commonwealth Edison Company
1400 Opus Place, Suite 400
Downers Grove, IL 60515

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room. Should you have any questions concerning this inspection, I would be pleased to discuss them with you.

Sincerely, **Original signed by**

James M. Taylor
Executive Director for Operations

Dockets: 50-237; 50-249

Enclosure:
NRC Inspection Report
50-237/96-201; 50-249/96-201
w/Appendices

cc w/enclosure: E-Mail report to NRR Event Tracking System (IPAS)
See next page E-Mail report to R. Correia (RPC)

bcc w/Enclosure:
Chairman Jackson
Commissioner Rogers
Commissioner Dicus
Commissioner McGaffigan
Commissioner Diaz
Public

JTaylor, EDO, O-17G21
HThompson, EDO, O-17G21
BMcCabe, EDO, O-17G21
FCongel, AEOD, T-4D28
EJordan, AEOD, T-4D18
ATHadani, NRR, O-12G18
RGallo, NRR, O-9A1
WOlmstead, OGC, O-15B18
JLieberman, OE, O-7H5
GCaputo, OI, O-2G5
HMiller, RI
SEbnetter, RII
PHiland, RIII
JLynch, RIII
LCallan, RIV
WJones, RIV
Dresden File, RIV
CVanderniet, SRI, Dresden

DCD/CentralFiles
JMilhoan, EDO, O-17G21
VMcCree, EDO, O-17G21
EDO R/F, O-17G21
SRubin, AEOD, T-4D28
FMiraglia, NRR, O-12G18
RZimmerman, NRR, O-12G1
FGillespie, NRR, O-12G18
RBangart, OSP, O-3D23
WBeecher, OPA, O-2G5
HBell, OIG, O-3E4
JLinville, RI
ABeach, RIII
JHopkins, RIII
PAO RIII (2)
JPellet, RIV
HWong, RIV
ISI Team Members
LTremper, OC/LFDCB, T-9E10

DOCUMENT NAME: P:\DRESDEN\FINAL\96201.FNL

OPS:LEADER	MNT:LEADER	M&O:LEADER	ENG:LEADER	TL
JLPellet	WJones	JLinville	HWong	ATHowell
/ /96	/ /96	/ /96	/ /96	/ /96

TM	DEDR	EDO
SJCollins	JLMilhoan	JMTaylor
/ /96	/ /96	/ /96

OFFICIAL RECORD COPY

E-Mail report to NRR Event Tracking System (IPAS)
 E-Mail report to R. Correia (RPC)

bcc w/Enclosure:

Chairman Jackson
 Commissioner Rogers
 Commissioner Dicus
 Commissioner McGaffigan
 Commissioner Diaz

Public

JTaylor, EDO, O-17G21
 HThompson, EDO, O-17G21
 BMcCabe, EDO, O-17G21
 FCongel, AEOD, T-4D28
 EJordan, AEOD, T-4D18
 AThadani, NRR, O-12G18
 RGallo, NRR, O-9A1
 WOlmstead, OGC, O-15B18
 JLieberman, OE, O-7H5
 GCaputo, OI, O-2G5
 HMiller, RI
 SEbnetter, RII
 PHiland, RIII
 JLYnch, RIII
 LCallan, RIV
 WJones, RIV
 Dresden File, RIV
 CVanderniet, SRI, Dresden

DCD/CentralFiles

JMilhoan, EDO, O-17G21
 VMcCree, EDO, O-17G21
 EDO R/F, O-17G21
 SRubin, AEOD, T-4D28
 FMiraglia, NRR, O-12G18
 RZimnerman, NRR, O-12G1
 FGillespie, NRR, O-12G18
 RBangart, OSP, O-3D23
 WBeecher, OPA, O-2G5
 HBell, OIG, O-3E4
 JLinville, RI
 ABeach, RIII
 JHopkins, RIII
 PAO RIII (2)
 JPellet, RIV
 HWong, RIV
 ISI Team Members
 LTremper, OC/LFDCB, T-9E10

DOCUMENT NAME: P:\DRESDEN\FINAL\96201.FNL

OPS:LEADER	MNT:LEADER	M&O:LEADER	ENG:LEADER	TL
JLPellet <i>[Signature]</i>	WJones <i>[Signature]</i>	JLinville <i>[Signature]</i>	HWong <i>[Signature]</i>	ATHowell <i>[Signature]</i>
12/1/96	12/1/96	12/1/96	12/1/96	12/1/96

TM	DEDR	EDO
SJCollins <i>[Signature]</i>	JLMilhoan	JMTaylor
12/1/96	1/1/96	1/1/96

OFFICIAL RECORD COPY