

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Joseph M. Farley - Unit 1

DOCKET NUMBER (2)

0 5 0 0 0 3 4 8 1 OF 0 1

TITLE (4)

Diesel Generator Inadvertently Started

EVENT DATE (5)
MONTH DAY YEAR
0 8 2 8 8 5 8 5
LER NUMBER (6)
YEAR SEQUENTIAL NUMBER REVISION NUMBER
0 1 4 0 0
REPORT DATE (7)
MONTH DAY YEAR
0 9 2 3 8 5
OTHER FACILITIES INVOLVED (8)
FACILITY NAME: J.M. Farley - Unit 2
DOCKET NUMBER(S): 0 5 0 0 0 3 6 4THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)
OPERATING MODE (9) 1
POWER LEVEL (10) 0 9 9
20.402(b) 20.406(c) X 50.73(a)(2)(iv) 73.71(b)
20.406(a)(1)(i) 50.36(c)(1) 50.73(a)(2)(v) 73.71(c)
20.406(a)(1)(ii) 50.36(c)(2) 50.73(a)(2)(vii) OTHER (Specify in Abstract below and in Text, NRC Form 366A)
20.406(a)(1)(iii) 50.73(a)(2)(ii) 50.73(a)(2)(viii)(A)
20.406(a)(1)(iv) 50.73(a)(2)(iii) 50.73(a)(2)(viii)(B)
20.406(a)(1)(v) 50.73(a)(2)(iii) 50.73(a)(2)(ix)

LICENSEE CONTACT FOR THIS LER (12)

NAME J. D. Woodard
TELEPHONE NUMBER
AREA CODE 210 15 819 91-1511516

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURE	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) X NO
EXPECTED SUBMISSION DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 1423 on 8-28-85, an inadvertent actuation of Engineered Safety Feature equipment occurred when the 2C diesel generator started automatically due to a technician accidentally bumping the emergency start relay. The diesel generator came to rated frequency and voltage following receipt of the start signal. All equipment functioned as designed.

A technician was working on the temperature controller for the 2C diesel generator jacket water heater. While tracing the wiring within the relay terminal box, the technician accidentally bumped the manual operator of the emergency start relay causing the diesel generator to start. The diesel generator was shut down in accordance with the operating procedure.

This event was caused by personnel error. The technician involved has been counseled.

8510020001 850923
PDR ADOCK 05000348
S PDR

IE22

Mailing Address
Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6090

R. P. McDonald
Senior Vice President
Flintridge Building



September 23, 1985

Docket No. 348

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 1, Licensee Event Report No. LER 85-014-00 is forwarded in accordance with 10CFR50.73 to provide 30 day written notification of the occurrence.

If you have any questions, please advise.

Yours very truly,

A handwritten signature in dark ink, appearing to read 'R. P. McDonald'.

R. P. McDonald

RPM:sam

Enclosure

xc: IE, Region II

IE22
1/1