


IEO 1/10

When the QC evaluation was completed, approximately eight hours from the time QC was notified of the crack indication, a Deviation Report was issued and a hold tag was placed adjacent to the weld. To prevent recurrence of discrepancies of this type, Pullman Power Products Procedure XV-4 will be revised to clarify the use of hold tags relative to evaluation work carried from one shift to another. Personnel affected by the procedure change will be indoctrinated to the new requirements. Georgia Power Company expects to complete these corrective actions by April 15, 1985.

This response contains no proprietary information and may be placed in the NRC Public Document Room.

Yours truly,



D. O. Foster

REF/DOF/tdm

xc: U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

R. J. Kelly
R. E. Conway
G. F. Head
J. T. Beckham
R. A. Thomas
D. E. Dutton
W. F. Sanders (NRC)
R. H. Pinson
B. M. Guthrie
E. D. Groover
R. W. McManus

J. A. Bailey
O. Batum
H. H. Gregory
W. T. Nickerson
D. R. Altman
D. L. Kinnsch (BPC)
J. L. Vota (W)
L. T. Gucwa
C. E. Belflower
F. B. Marsh (BPC)

G. Bockhold
P. D. Rice
C. S. McCall (OPC)
E. L. Blake, Jr.
(Shaw, et. al.)
J. E. Joiner
(Troutman, et. al.)
D. C. Teper (GANE)
L. Fowler (LEAF)
T. Johnson (ECPG)