

## UNIT SHUTDOWNS AND POWER REDUCTIONS - Corrected

REPORT MONTH: September 1996

DOCKET NO: 50-362  
 UNIT NAME: SONGS - 3  
 DATE: January 15, 1997  
 COMPLETED BY: C. E. Williams  
 TELEPHONE: (714) 368-6707

No.	Date	Type <sup>1</sup>	Duration (Hours)	Reason <sup>2</sup>	Method of Shutting Down Reactor <sup>3</sup>	LER No.	System Code <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
93	9/24/96	S	164.3	A	1	96-004*		AB TW	Investigate unidentified RCS leakage and repair failed RCS thermowell.

\* This LER required due to pressure boundary leakage

<sup>1</sup>F-Forced  
<sup>1</sup>S-Scheduled

<sup>2</sup>Reason:  
 A-Equipment Failure (Explain)  
 B-Maintenance or Test  
 C-Refueling  
 D-Regulatory Restriction  
 E-Operator Training & License Examination  
 F-Administrative  
 G-Operational Error (Explain)  
 H-Other (Explain)

<sup>3</sup>Method:  
 1-Manual  
 2-Manual Scram.  
 3-Automatic Scram.  
 4-Continuation from  
 Previous Month  
 5-Reduction in the Average  
 Daily Power Level of more  
 than 20% from the previous day  
 6-Other (Explain)

<sup>4</sup>IEEE Std 805-1984  
<sup>5</sup>IEEE Std 803A-1983

9701220389 970115  
 PDR ADOCK 05000361  
 R PDR