

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

July 3, 1985

05 JUL 9 4:33 PM

Dr. J. Nelson Grace
Regional Administrator
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30323


SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
Special Report (SPR 85-008)

Dear Dr. Grace:

Attached is a Special Report for the Virgil C. Summer Nuclear Station. This Special Report is submitted pursuant to the requirements of Section 6 of the Technical Specifications.

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

RJB:OWD/lcd
Attachment

cc: V. C. Summer	K. E. Nodland
T. C. Nichols, Jr./O. W. Dixon, Jr.	R. A. Stough
E. H. Crews, Jr.	G. Percival
E. C. Roberts	C. W. Hehl
W. A. Williams, Jr.	J. B. Knotts, Jr.
D. A. Nauman	S. D. Hogge
Group Managers	I&E Washington
O. S. Bradham	Document Management
C. A. Price	Branch
S. R. Hunt	INPO Records Center
J. F. Heilman	ANI Library
C. L. Ligon (NSRC)	NPCF
	File

Dr. J. Nelson Grace
SPR 85-008
Page Two
July 3, 1985

EVENT DESCRIPTION

On June 6, 1985, while performing an Appendix R Audit, three (3) discrepancies were identified.

- 1) A seismic opening in the floor of the Intermediate Building (IB) Room 63-01 was found to be unsealed.
- 2) A conduit passing through the floor of IB Room 26-02 had a one inch gap between the floor and the triple wrap of kaowool.
- 3) An error was made in the Fire Watch Log with respect to a room required for the hourly inspections, i.e., IB Room 12-07 was designated in the logs and inspected hourly instead of IB Room 12-02 as was required.

ACTION TAKEN

- 1) Smoke detectors were verified operable and a one hour fire watch patrol was established. Repair of the opening will be completed during the next outage of sufficient duration, because scaffolding required for accessibility to the opening will impact the operability of the adjacent safety-related equipment.
- 2) Smoke detectors were verified operable, and a one hour fire watch patrol was established. Repair was completed, and the barrier was declared operable on June 10, 1985.
- 3) The Fire Watch Log was immediately corrected. Access to IB Room 12-07 is via IB Room 12-02; therefore, the hourly coverage of the area was in effect accomplished.