

DMB



Docket No. 50-346

License No. NPF-3

Serial No. 1-563

August 9, 1985

JOE WILLIAMS, JR.
Senior Vice President--Nuclear
(419) 249-2300
(419) 249-5223

Mr. James G. Keppler
Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

PRIORITY ROUTING	
First	Second
✓ RA	✓ MC
✓ DRP	✓ EIC
✓ DRS	✓ SGA
✓ DRSS	✓ ML
✓ DRMA	✓ OL
	✓ OT
	✓ PAO

FILE *he*

Dear Mr. Keppler:

Enclosed is Revision 4 of the Safety-Related Piping System Support and Hanger Discrepancies Summary Report for the Davis-Besse Nuclear Power Station Unit No. 1. As requested by your Staff, Toledo Edison is updating this report weekly and submitting it to your office to keep your Staff notified in writing of any new discrepancies identified on safety-related piping system hangers or supports. Under Revision 4, one discrepant item has been added to this report, i.e., a loose anchor bolt nut on anchor A004.

This report also provides the status of discrepancies with regards to their disposition. Since Revision 3 of this report was submitted on July 26, 1985, ten Nonconformance Report items and one Surveillance Report item have been dispositioned.

Very truly yours,

Joe Williams, Jr.
W:DRW:lah
enclosure

cc: DB-1 NRC Resident Inspector
D. Danielson, NRC Region III
I. N. Jackiw, NRC Region III

AUG 12 1985

8508160090 850809
PDR ADOCK 05000346
P PDR

TEO 1/1