

January 30, 1997

Ms. Irene M. Johnson, Acting Manager
Nuclear Regulatory Services
Commonwealth Edison Company
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION REGARDING SECOND 10-YEAR
INSERVICE INSPECTION PROGRAM - BYRON STATION (TAC NOS. M94830 AND
M94831)

Dear Ms. Johnson:

On February 23, 1996, Commonwealth Edison Company (ComEd) submitted its second 10-year Inservice Inspection (ISI) program and associated relief requests. In its submittal, ComEd requested expedited review for Relief Requests 12R-11 and 12R-12. Relief Request 12R-11 was subsequently withdrawn by ComEd on June 12, 1996; we authorized Relief Request 12R-12 on July 22, 1996.

Requests for Additional Information (RAI) were issued on June 13, 1996, October 16, 1996, and December 13, 1996. ComEd provided its response to the first RAI on August 12, 1996, and its response to the second and third RAIs on December 16, 1996. During the continuation of our review, we have identified the need for further information as discussed in the enclosed RAI. Please provide your response to the questions within 60 days of receipt of this request.

Sincerely,

ORIGINAL SIGNED BY:
George F. Dick, Jr., Project Manager
Project Directorate III-2
Division of Reactor Projects - III/IV
Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455

Enclosure: RAI

cc w/encl: See next page

Distribution:

Docket File	PUBLIC
PDIII-2 r/f	J. Roe, JWR
E. Adensam, EGA1	R. Capra, RAC1
G. Dick, GFD	C. Moore, ACM
OGC, 015B18	ACRS, T2E26
R. Lanksbury, RIII	R. Wessman, 07E23
F. Grubelich, 07E23	

DOCUMENT NAME: BYRON\BY94830.RAI

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

OFFICE	PM:PDIII-2	E	LA:PDIII-2	C	EMEB	PD:PDIII-2	C
NAME	G. DICK		C. MOORE		R. WESSMAN	R. CAPRA	
DATE	01/29/97		01/29/97		01/30/97	01/30/97	

OFFICIAL RECORD COPY

9702040280 970130
PDR ADOCK 05000454
G PDR



UNITED STATES
NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

January 30, 1997

Ms. Irene M. Johnson, Acting Manager
Nuclear Regulatory Services
Commonwealth Edison Company
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION REGARDING SECOND 10-YEAR
INSERVICE INSPECTION PROGRAM - BYRON STATION (TAC NOS. M94830 AND
M94831)

Dear Ms. Johnson:

On February 23, 1996, Commonwealth Edison Company (ComEd) submitted its second 10-year Inservice Inspection (ISI) program and associated relief requests. In its submittal, ComEd requested expedited review for Relief Requests 12R-11 and 12R-12. Relief Request 12R-11 was subsequently withdrawn by ComEd on June 12, 1996; we authorized Relief Request 12R-12 on July 22, 1996.

Requests for Additional Information (RAI) were issued on June 13, 1996, October 16, 1996, and December 13, 1996. ComEd provided its response to the first RAI on August 12, 1996, and its response to the second and third RAIs on December 16, 1996. During the continuation of our review, we have identified the need for further information as discussed in the enclosed RAI. Please provide your response to the questions within 60 days of receipt of this request.

Sincerely,

A handwritten signature in cursive script, reading "George F. Dick, Jr.", is written over the typed name.

George F. Dick, Jr., Project Manager
Project Directorate III-2
Division of Reactor Projects - III/IV
Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455

Enclosure: RAI

cc w/encl: See next page

I. Johnson
Commonwealth Edison Company

cc:

Michael I. Miller, Esquire
Sidley and Austin
One First National Plaza
Chicago, Illinois 60603

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
801 Warrenville Road
Lisle, Illinois 60532-4351

Illinois Department of
Nuclear Safety
Office of Nuclear Facility Safety
1035 Outer Park Drive
Springfield, Illinois 62704

Document Control Desk-Licensing
Commonwealth Edison Company
1400 Opus Place, Suite 400
Downers Grove, Illinois 60515

Mr. William P. Poirier, Director
Westinghouse Electric Corporation
Energy Systems Business Unit
Post Office Box 355, Bay 236 West
Pittsburgh, Pennsylvania 15230

Joseph Gallo
Gallo & Ross
1250 Eye St., N.W.
Suite 302
Washington, DC 20005

Howard A. Learner
Environmental law and Policy
Center of the Midwest
203 North LaSalle Street
Suite 1390
Chicago, Illinois 60601

U.S. Nuclear Regulatory Commission
Byron Resident Inspectors Office
4448 North German Church Road
Byron, Illinois 61010-9750

Ms. Lorraine Creek
Rt. 1, Box 182
Manteno, Illinois 60950

Byron Station
Unit Nos. 1 and 2

Chairman, Ogle County Board
Post Office Box 357
Oregon, Illinois 61061

Mrs. Phillip B. Johnson
1907 Stratford Lane
Rockford, Illinois 61107

Attorney General
500 South Second Street
Springfield, Illinois 62701

EIS Review Coordinator
U.S. Environmental Protection Agency
77 W. Jackson Blvd.
Chicago, Illinois 60604-3590

Commonwealth Edison Company
Byron Station Manager
4450 North German Church Road
Byron, Illinois 61010

Kenneth Graesser, Site Vice President
Byron Station
Commonwealth Edison Station
4450 N. German Church Road
Byron, Illinois 61010

REQUEST FOR ADDITIONAL INFORMATION

SECOND 10-YEAR INSERVICE INSPECTION INTERVAL

COMMONWEALTH EDISON COMPANY

BYRON STATION, UNITS 1 AND 2

DOCKET NOS. STN 50-454 AND STN 50-455

The following questions pertain to Relief Request 12R-13.

1. The requirements of OMa-1988, Part 4, Section 2, per IWF-5200 pertain to preservice (pre-operational) examination of snubbers. In Relief Request 12R-13, the licensee states that similar requirements are included in the technical specifications (TS). Please identify the TS location for these requirements and describe their similarity with Part 4, Section 2 requirements or modify the relief request accordingly.
2. IWF-5400 requirements defer to OMa-1988, Part 4, and IWF-4000 for repair and IWF-7000 for the replacement of snubbers. The Byron relief request states that the repair and replacement requirements of IWF-4000 and 7000 will be met and snubber repair and replacement will be performed per the TSs in lieu of OMa-1988, Part 4, requirements. Please identify the TS location(s) that defines these requirements and describe how they replace the OMa-1988, Part 4, requirements.

ENCLOSURE