



85 JUL 30 A 9:15

**Florida
Power**
CORPORATION

July 24, 1985
3F0785-30

Dr. J. Nelson Grace
Regional Administrator, Region II
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, GA 30323

Subject: Crystal River Unit 3
Docket No. 50-302
Operating License No. DPR-72
Special Report 85-02
Supplement 1

Dear Sir:

Enclosed is Supplement 1 to Special Report 85-02 which is submitted in accordance with Technical Specification 6.9.2.

Should there be any questions, please contact this office.

Sincerely,

G. R. Westafer
Manager, Nuclear Operations
Licensing and Fuel Management

AEF/feb

Enclosure

cc: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8508280085 850724
PDR ADOCK 05000302
S PDR

1622
1/1
1619

FLORIDA POWER CORPORATION

SUPPLEMENT I SPECIAL REPORT 85-02

Special Report 85-02 reported the inoperability of the Halon portion of the fire suppression system at Crystal River Unit 3. The report listed the cause of the Halon subsystem inoperability as modification work in progress and estimated the subsystem to be restored to operability by July 1, 1985. This supplement is provided because the Halon subsystem was not restored to operability by July 1, 1985.

The July 1, 1985 date was not met due to extensive additional work necessary to complete the modifications discussed in Special Report 85-02. This additional work was required because of the unanticipated difficulties in dealing with the asbestos materials in the areas being modified. The presence of asbestos made additional safety precautions necessary and significantly hindered work progress on the modifications.

Fire watches have been continually monitoring the area normally protected by the Halon subsystem and will continue to do so until the subsystem is restored to operability. The subsystem and will be operable prior to the plant being brought back up from refueling.