

Public

IE-01

January 28, 1997

Mr. E. Watzl, Vice President  
Nuclear Generation  
Northern States Power Company  
414 Nicollet Mall  
Minneapolis, MN 55401

SUBJECT: NRC INSPECTION REPORT NO. 50-282/96016, 50-306/96016

Dear Mr. Watzl:

On January 7, 1997, the NRC completed an inspection at your Prairie Island Nuclear Generating Plant. The enclosed report presents the results of that inspection.

During the 7-week period covered by this inspection, your conduct of activities at the Prairie Island facilities was generally acceptable. However, a concern with operator performance during surveillance activities was identified in the three most recent resident inspector reports. During this report period an additional operator error during surveillance activities was identified. Your staff also identified a case where operators had performed an incorrect surveillance test. Both of these errors were due to inadequate self-checking by licensed operators. In addition, the NRC identified that many of your surveillance procedures were not written in the format specified by your writer's guide. We are concerned that this could lead to additional errors during performance.

An inadvertent boron dilution of the reactor coolant system occurred during recovery from a maintenance activity due to an incorrectly specified valve position. While operators detected the dilution in a timely manner, the incorrect valve position had not been identified by two licensed operators during their reviews of the documentation prior to returning the letdown purification system to service. This was another example of inadequate self-checking similar to the surveillance errors discussed above.

We understand that corrective actions for the errors discussed above have been initiated in response to the cited violation in our last report and recent Licensee Event Reports. Therefore we elected to provide you a reasonable time for corrective action implementation before re-citing similar events involving operator errors, and the issues discussed above were considered non-cited violations. However, we remain concerned with weaknesses in operator performance and will closely monitor the effectiveness of those actions.

9702110209 970128  
PDR ADOCK 05000282  
G PDR

E. Watzl

-2-

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room (PDR).

Sincerely,

/s/ J. A. Grobe for  
J. L. Caldwell, Director  
Division of Reactor Projects

Docket Nos.: 50-282, 50-306  
License Nos: DPR-42, DPR-60

Enclosure: Inspection Report 50-282/96016, 50-308/96016

cc w/encl: Plant Manager, Prairie Island  
John W. Ferman, Ph.D.,  
Nuclear Engineer, MPCA  
State Liaison Officer, State  
of Minnesota  
State Liaison Officer, State  
of Wisconsin  
Tribal Council  
Prairie Island Dakota Community

Distribution:

Docket File w/encl  
PUBLIC IE-01 w/encl  
OC/LFDCB w/encl  
SRI Prairie Island w/encl  
Monticello w/encl  
H. B. Clayton, w/encl  
W. L. Axelson, w/encl

DRP w/encl  
RIII PRR w/encl  
Prairie Island PM, NRR w/encl  
CAA1 w/encl (E-mail)  
A. B. Beach, w/encl

DOCUMENT NAME: R:\INSPRPTS\POWERS\PRAI\PRA96016.DRP

To receive a copy of this document, indicate in the box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII	RIII			
NAME	Jacobson	Caldwell			
DATE	1/28/97	1/28/97			

OFFICIAL RECORD COPY