

Detroit  
Edison

Douglas R. Gipson  
Senior Vice President  
Nuclear Generation

Fermi 2  
6400 North Dixie Highway  
Newport, Michigan 48166  
(313) 586-5249

10CFR50.73  
November 4, 1996  
NRC-96-0092

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Reference: 1) Fermi 2  
NRC Docket No. 50-341  
NRC License No. NPF-43  
  
2) NRC Letter to Detroit Edison, "Amendment No. 51 To  
Facility Operating License No. NPF-43: (TAC No. 69835),"  
Dated February 20, 1990.

Subject: Licensee Event Report (LER) No. 96-014

Pursuant to 10 CFR 50.73, Detroit Edison is submitting the enclosed LER No. 96-014 regarding the failure of the Residual Heat Removal Service Water reservoir cross-connect valve to open as required to satisfy a Technical Specification Limiting Condition of Operation. This is being reported as a condition prohibited by the Fermi 2 Technical Specifications.

The following commitments are made in this LER.

1. The E1150F601A valve operator will be repaired prior to restart from the fifth refueling outage by providing a small recess for the spline bushing set screw and the set screw will be secured in place. The other cross-connect valves will also be modified with the set screw recess.
2. Operations will prepare a lessons learned document and discuss this event with shift operations personnel by December 19, 1996.
3. The bus shutdown procedures will be evaluated to determine if more detail regarding specific component impacts should be added. The bus shutdown procedures will be revised, if necessary, prior to the start of the sixth refueling outage.

120029

9611140034 961104  
PDR ADOCK 05000341  
S PDR

JE22/1

November 4, 1996


NRC-96-0092

Page 2

4. The Ultimate Heat Sink cross-connect valve surveillance procedures will be evaluated to determine the need to provide positive indication that a cross connect path is established when the associated cross-connect path valves are in the open position as indicated in the control room. These procedures will be revised, if necessary, prior to the next quarterly performance of the surveillance after restart from the fifth refueling outage.

If you have any questions, please contact Ken Riches at (313) 586-5529.

Sincerely,



cc: A. B. Beach  
M. J. Jordan  
A. J. Kugler  
A. Vogel  
M. V. Yudas, Jr.  
Region III  
Wayne County Emergency Management Division