

Report Period: August, 1996

UNIT SHUTDOWNS/REDUCTIONS
(UNIT 2)

* BYRON *

<u>No.</u>	<u>Date</u>	<u>Type</u>	<u>Hours</u>	<u>Reason</u>	<u>Method</u>	<u>LER Number</u>	<u>System</u>	<u>Component</u>	<u>Cause & Corrective Action To Prevent Recurrence</u>
2	8/08/96	F	253:20	A	1		MS	Stm Generator	Forced Outage B2F17 Due To Increased Leak Rate In The 2A S/G
3	8/19/96	S	312:00	C	4				Began Refueling Outage B2R06

* Summary *

<u>TYPE</u>	<u>Reason</u>	<u>Method</u>	<u>System & Component</u>
F-Forced	A-Equip Failure	1-Manual	Exhibit F & H
S-Sched	F-Admin	2-Manual Scram	Instructions for
	B-Maint or Test	3-Auto Scram	Preparation of
	C-Refueling	4-Continued	Data Entry Sheet
	H-Other	5-Reduced Load	Licensee Event Report
	D-Regulatory Restriction	9-Other	(LER) File (NUREG-0161)
	E-Operator Training		
	& License Examination		

9611260160 961108
PDR ADOCK 05000454
R PDR