



**Florida
Power**

CORPORATION
Crystal River Unit 3
Docket No. 50-302

November 25, 1996
3F1196-15

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555-0001

Subject: Licensee Event Report (LER) 96-018-01

Dear Sir:

Please find the enclosed Licensee Event Report (LER) 96-018-01 concerning inadequate containment penetration surveillance procedures.

This supplemental report is submitted by Florida Power Corporation in accordance with 10 CFR 50.73 and identifies changes resulting from the comprehensive review of flow diagrams, procedures, design basis documents and licensing basis information required to be performed in accordance with actions established by the original LER. As a result, included in this supplement is one additional valve and a blind flange discovered to be omitted from the required surveillance procedures for verification that containment penetration valves and blind flanges are in their required positions. Note that one valve previously identified in the original LER was removed by this supplement as it had been erroneously identified as not being included in the surveillance procedure.

Sincerely,

G. L. Boldt
Vice President, Nuclear Production

GLB/TWC

Attachment
xc: Regional Administrator, Region II
Project Manager, NRR
Senior Resident Inspector

9612030238 961125
PDR ADOCK 05000302
S PDR

IE22/1