

D m B

Docket No. 50-346

License No. NPF-3

Serial No. 1-571

September 6, 1985



JOE WILLIAMS, JR.
Senior Vice President—Nuclear
(419) 249-2300
(419) 249-5223

Mr. James G. Keppler
Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

orig + 1

PRIORITY ROUTING	
First	Second
RA	
DRW	✓
ONS	
DRS	
DRNA	
FILE	<i>lan</i>

Dear Mr. Keppler:

Enclosed is Revision 7 of the Safety-Related Piping System Support and Hanger Discrepancies Summary Report for the Davis-Besse Nuclear Power Station Unit No. 1. Toledo Edison is updating this report weekly and submitting it to your office to keep your Staff notified in writing of any new discrepancies identified on safety-related piping system hangers or supports.

Revision 7 includes discrepancies identified on hangers and supports on the Low Pressure Injection system piping and High Pressure Injection system piping. These discrepancies have been recently identified under Toledo Edison's expanded inspection program of hangers and supports on safety-related piping systems.

Very truly yours,

Joe Williams, Jr.
JW:DRW:lah
enclosure

cc: DB-1 NRC Resident Inspector
D. Danielson, NRC Region III
I. N. Jackiw, NRC Region III

8509160167 850906
PDR ADOCK 05000346
P PDR

SEP 9 1985

11 IE 01