

U.S. NUCLEAR REGULATORY COMMISSION
REGION I

Report No. 30-20982/85-03

Docket No. 030-20982

License No. 37-23370-01 Priority 1 Category C1

Licensee: North American Inspection, Inc.
P.O. Box 88
Laurys Station, PA 18059

Enforcement Conference at: King of Prussia, Pennsylvania

Enforcement Conference Conducted: July 9, 1985

Prepared by: F. Costello 8/28/85
F. Costello, Senior Radiation Specialist date

Conference Summary: Enforcement Conference held at the Region I office in King of Prussia on July 9, 1985 to discuss the apparent violations identified during an inspection conducted June 13, 14, and 26, 1985, and licensee corrective actions.

8509130318 850909
REG1 LIC30
37-23370-01 PDR

1. Attendance

North American Inspection, Inc.

Robert K. Shumway, President
Sam Hopkins, Consultant

NRC Region I

J. Allan, Deputy Regional Administrator
T. Martin, Director, Division of Radiation Safety and Safeguards
J. Joyner, Chief, Nuclear Materials Safety and Safeguards Branch
D. Holody, Enforcement Specialist
F. Costello, Senior Radiation Specialist
J. Gutierrez, Regional Attorney

2. Summary

On July 9, 1985, licensee representatives met with representatives of the Nuclear Regulatory Commission, Region I in King of Prussia, Pennsylvania.

During the meeting, Region I representatives discussed the apparent violations identified during the inspection conducted on June 13, 14 and 26, 1985 and their concern that the Laurys Station facility had been used for radiography involving licensed materials after a commitment had been made during Enforcement Conference 30-20982/84-02 to cease using this facility. Region I representatives emphasized the importance of ensuring the accuracy of all records required by the license and all information provided to the NRC.

Licensee representatives acknowledged that a need existed for a review of their program by another outside consultant and expressed their willingness to cease using the Laurys Station facility for radiography. They stated that the use that occurred was a mistake because the radiographer involved had been expected to use an x-ray machine rather than the iridium-192 source which he used.

The licensee provided a copy of the training of Mr. David Hopkins which was not available during the June, 1985 inspection.

The licensee president stated that he would contact Region I by July 31, 1985 and describe his plans to review and upgrade the radiation safety program.

Enforcement options available to the NRC were discussed.