



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

Dm/B

January 21, 1986

Mr. James G. Keppler
Regional Administrator
U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

SUBJECT: Braidwood Station Units 1 and 2
10 CFR 50.55(e) No. 85-03 Final Report
Instrumentation Installation
Reverification Program
NRC Docket Nos. 50-456/457

REFERENCES (a): D. H. Smith letter to J. G. Keppler
dated February 27, 1985

(b): A. D. Miosi letter to J. G. Keppler
dated May 7, 1985

Dear Mr. Keppler:

Reference (a) provided information concerning a deficiency reportable pursuant to 10 CFR 50.55(e) regarding deficiencies identified during the conduct of the Instrumentation Installation Reverification Program at our Braidwood Station. The purpose of this letter is to inform you the corrective actions identified by Commonwealth Edison to address this issue are now complete. This is considered to be a final report.

As previously identified under the Instrumentation Retrofit Verification (IRV) program (QCP-B32), all safety-related ASME Section III and class H instrument installation made prior to February 1984 were reinspected and reworked (as necessary). A review of the associated documentation was done to verify these installations conform to the appropriate specification requirements. The results of this IRV program show these installations to be acceptable. The results of the IRV program and associated documentation are available onsite for inspection.

Very truly yours,

8602030273 860121
PDR ADOCK 05000456
S PDR

Anthony D. Miosi

A.D. Miosi
Nuclear Licensing Administrator

ADM/

cc: NRC Resident Inspector - Braidwood

Director of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

JAN 24 1986 1/0
IE27

1165K