



TOLEDO
EDISON

August 16, 1985

JOE WILLIAMS, JR.
Senior Vice President—Nuclear
(419) 249-2300
(419) 249-5223

Mr. James G. Keppler
Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

PRIORITY ROUTING

FILE	SECOND
<i>[initials]</i>	<i>[initials]</i>
<i>[initials]</i>	<i>[initials]</i>
<i>[initials]</i>	<i>[initials]</i>
DSSS	OL
DRMA	OT
	PED

FILE *[signature]*

Dear Mr. Keppler:

Enclosed is Revision 5 of the Safety-Related Piping System Support and Hanger Discrepancies Summary Report for the Davis-Besse Nuclear Power Station Unit No. 1. As requested by your Staff, Toledo Edison is updating this report weekly and submitting it to your office to keep your Staff notified in writing of any new discrepancies identified on safety-related piping system hangers or supports. No new discrepancies were identified on safety-related piping system hangers or supports from August 8, 1985 to August 13, 1985. Therefore, there are no additions to this report.

This report also provides the status of discrepancies with regards to their disposition. Since Revision 4 of this report (Serial No. 1-562) was submitted on August 2, 1985, 20 Nonconformance Report items and one Surveillance Report item have been dispositioned. Accordingly, of the presently identified discrepant items, only two (2) Nonconformance Report items remain to be dispositioned.

Very truly yours,

Joe Williams Jr. from

JW:DRW:lah
enclosure

cc: DB-1 NRC Resident Inspector
D. Danielson, NRC Region III
I. N. Jackiw, NRC Region III

AUG 21 1985

8512090257 850816
PDR ADOCK 05000346
S PDR