

DRAFT 2  
07/18/84

WATERFORD OPEN ISSUE

Task: A-23b

Reference No.: 4-83-A-81/4b (page 7)

Characterization: It is alleged that the piping installation procedures of Tompkins-Beckwith, Inc. (T-B) did not contain provisions to assure that supports and hangers were maintained in the design-verified condition, and that as a consequence, hanger removals or modifications may have been made without conformance to an approved procedures. It is also alleged that T-B audits were not planned.

Initial Assessment of Significance: [Potential violation of code, weld failure.] 4

Source: Information provided by anonymous source fall of 1982.

Approach to Resolution:

1. Review Watertford 3 Final Safety Analysis Report.
2. Review applicable ASME III Code section.
3. Review applicable procedures, audits, and NCRs.
4. Review Significant Construction Deficiency 60.
5. Review NRC Inspection Report No. 50-382/82-14 and associated enforcement action.

Status:

Review Lead: L. Shao

Support: N/A

Estimated Resources: 2 man-days

Estimated Completion: April 10, 1984

CLOSURE:

8510030078 840718  
PDR ADOCK 05000382  
E PDR

Document Name:  
A-23B

Requestor's ID:  
JOHNNIE

Author's Name:  
LShao/jkh

Document Comments:  
Waterford Open Issue - A-23b

✓ 4

Document Name:  
A-23B

Requestor's ID:  
JOHNNIE

Author's Name:  
LShao/jkh

Document Comments:  
Waterford Open Issue - A-23b



*Retype Draft 2*

WATERFORD OPEN ISSUE

Task: A-23b

Reference No.: 4-83-A-81/4<sup>b</sup> (page 7)

Characterization: It is alleged that the piping installation procedures of Tompkins-Beckwith, Inc. (T-B) did not contain provisions to assure that supports and hangers were maintained in the design-verified condition, and that as a consequence, hanger removals or modifications may have been made without conformance to an approved procedures. It is also alleged that T-B audits were not planned.

Initial Assessment of Significance: [Potential violation of code, weld failure.] 4

Source: Information provided by anonymous source fall of 1982.

Approach to Resolution:

1. Review Waterford 3 Final Safety Analysis Report.
2. Review applicable ASME III Code section.
3. Review applicable procedures, audits, and NCRs.
4. Review Significant Construction Deficiency 60.
5. Review NRC Inspection Report No. 50-382/82-14 and associated enforcement action.

Status:

Review Lead: L. Shao

Support: N/A

Estimated Resources: 2 man-days

Estimated Completion: April 10, 1984

CLOSURE: