



**MIDWEST INSPECTION SERVICE, LTD.**

"Nondestructive Inspection"

"The Proof For Your Quality"

DMB COPY

48-162 96-01  
03010749

Sept. 24, 1985

Mr. D. G. Wiedeman, Chief  
Nuclear Materials Safety Section 1  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Gentleman;

Midwest Inspection Service, Ltd. respectfully submits the following information, corrections, and procedures adapted for compliance as they relate to radiation safety and activities conducted under our license:

1-10 CFR 34.25(b): Investigation revealed that this violation occurred due to a cut-back in operating number of sources. Prior operations of company show that 6 to 10 sources were being used. When business decline occurred, the excess sources (8) were put into storage. New source orders were not as numerous, therefore a number of sources were in storage for quite some period of time before being returned. Spring of 1985 reveals the operating average of 3 sources, with not one of them being returned to vendor without being with-in current leak test period.

1. No corrective action taken.
2. Additional statement typed on source storage control "Do not ship without current leak test" as a reminder to avoid further non-compliance.
3. Full compliance achieved 6-1-85.

2-10 CFR 20.401(b):

1. On Shipping/Receiving Form (Appendix A) #4 survey has the words "1 meter" added and an additional number and wording has been inserted to read "#5 survey (contact)".
2. This correction has been done on the master form, to avoid missing the recording of reading.
3. Full compliance achieved 7-1-85.

3-10 CFR 20.408:

1. Audit of all past employee's files as corrective action. Furnish to the Director, Office of Nuclear Regulatory Research terminated reports on those employees classified as technicians, Appendix B1. Waiting for response from Director on helper/worker classification, Appendix B2.

8510040201 B50924  
REG3 LIC30  
48-16296-01 PDR

SEP 27 1985


2. On Midwest Inspection Service Control Manual marked "Film Badge Reports" an additional label reading "Termination Reports" has been added as physical reminder.
3. Full compliance shall be met fifteen (15) days after response to Appendix B2.

4/5-10 CFR 71.5(a) and 49 CFR 173.25(a):

1. Corrective action taken: Vehicles of Midwest Inspection Service transporting license material have mounted approved containers specifically stating and marked "Radioactive Material Special Form, NOS UN 2974" and RADIOACTIVE YELLOW II or III whichever applicable.
2. Notation on lab inventory report source container properly marked as a check-off.
3. Compliance achieved 9-5-85.

I trust that the above corrections will bring Midwest Inspection Service, Ltd. and our license into compliance with your regulations.

Sincerely,



Donald Paschen, President

DP/sz

- 1-Date
- 2-Carrier
- 3-Location
- 4-Survey (1-meter)
- 5-Survey (contact)

Receiving

- 1-Certification
- 2-Decay curve
- 3-Leak Test
- 4-Survey (1-meter)
- 5-Survey (contact)

### Shipping

Source No. (Serial)	Received #5	Leak Test	Return Date	Shipping Criteria #5	Date Records Prepared for Storage	By Ini.
	1.			1.		
	2.			2.		
	3.			3.		
	1.			1.		
	2.			2.		
	3.			3.		
	1.			1.		
	2.			2.		
	3.			3.		
	1.			1.		
	2.			2.		
	3.			3.		
	1.			1.		
	2.			2.		
	3.			3.		
	1.			1.		
	2.			2.		
	3.			3.		
	1.			1.		
	2.			2.		
	3.			3.		
	1.			1.		
	2.			2.		
	3.			3.		