

ST. JOSEPH HOSPITAL
128 STRAWBERRY HILL AVENUE
STAMFORD, CONNECTICUT 06904
TELEPHONE 327-3500

0876

April 18, 1980

Mr. Joseph Del Medico
Material Licencing Branch
Division of Fuel Cycle & Material Safety
U.S. Nuclear Regulatory Commission
Washington, DC 20555

SECTION 6

10 55

Dear Sir:

As promised we have redesigned the air handling system to provide for a negative pressure environment and to isolate the scanning room from the remainder of the hospital facilities.

We were able to obtain 380 CFM of negative air over the total input of air. We have totally isolated this room of exposure to any other area but were able to maintain its present HVAC system with minor modifications. The only new piece of equipment is a new exhaust fan dedicated to this area. Revision three represents any changes to the present system.

Please review these plans and advise if this system meets with your approval and are in conformance with present codes.

I would welcome any suggestions you may have and would appreciate your earliest review of these drawings so we may implement this work as soon as possible.

Very truly yours,

James J. Vigilis
Director of Engineering

JJV:rp
Enc.

"OFFICIAL RECORD COPY"

ML19

8510310438 850926
REG1 LIC30
06-06922-02 PDR

COPIES SENT TO OFF. OF
INSPECTION AND ENFORCEMENT

OVERSIZE DOCUMENT PAGE PULLED

SEE APERTURE CARDS

NUMBER OF PAGES: 1

ACCESSION NUMBER(S):

8510310438-01

APERTURE CARD/HARD COPY AVAILABLE FROM RECORD SERVICES BRANCH, TIDC
FTS 492-8989

4/10/80

TELEPHONE OR VERBAL CONVERSATION RECORD

TIME

9

☒ A.M.
☐ P.M.

☐ INCOMING CALL

☒ OUTGOING CALL

☐ VISIT

PERSON CALLING

Delmedico

OFFICE/ADDRESS

PHONE NUMBER

EXTENSION

PERSON CALLED

Mr. Vigillio

OFFICE/ADDRESS

St. Joseph Hosp
CONVERSATION

PHONE NUMBER

EXTENSION

203-327-3500

SUBJECT

re # 97444

SUMMARY

The 330 CFM outgoing vent in scan room in ltr dtd 3/28/80 was achieved by blocking transfer grill into hot lab. 175 CFM exhaust through transfer grill is no longer applicable.

The 330 CFM vent is connected to the fume hood ductwork. Therefore, air from this vent is not recirculated.

REFERRED TO:

ML10

ACTION REQUESTED

"OFFICIAL RECORD COPY"

☐ ADVISE ME OF ACTION TAKEN.

INITIALS

DATE

ACTION TAKEN

INITIALS

DATE