

Appendix

NOTICE OF VIOLATION

Southwest X-Ray Clinic

License No. 21-16306-01

As a result of the inspection conducted on October 29, 1985, and in accordance with the General Policy and Procedures for NRC Enforcement Actions, (10 CFR Part 2, Appendix C), the following violations were identified:

1. 10 CFR 20.401(b) requires that a licensee maintain records showing the results of surveys required by 10 CFR 20.201(b), "Surveys."

Contrary to this requirement, the licensee failed to maintain records of surveys made prior to disposal of byproduct material. Specifically, the licensee failed to maintain records of surveys made of molybdenum-99/technetium-99m generators prior to disassembly and disposal.

This is a Severity Level V violation (Supplement IV).

2. 10 CFR 35.14(e)(1)(i) requires that any licensee who possesses sealed sources as calibration sources shall cause each sealed source to be tested for leakage and/or contamination at intervals not to exceed six months.


Contrary to this requirement, a 200 microcurie cesium-137 sealed calibration source and a 200 microcurie barium-133 sealed calibration source located at the 5321 Livernois Street clinic, were not leak tested for leakage and/or contamination from January 1985 through October 1985. This is a interval of greater than six months.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

NOV 13 1985

Dated _____


for D. G. Wiedeman, Chief
Nuclear Materials Safety
Section 1

8511180504 851113
REG3 LIC30
21-16306-01 PDR