

URANIUM REDUCTION COMPANY

INTER-OFFICE CORRESPONDENCE

To E. Sugar

From L. A. Palmer

Date July 26, 1939

Subject Wetting Dry Gums

Starting immediately, all dry gums are to be wet down with water as the time they are fed into the ore pot. Water should be added at the rate of from eight to sixteen gallons per minute.

The purpose of this procedure is to prevent dusting in the crushing building.

LAP:GJ

cc: B. B. W. W.

T. Jellison

Radiation File

9612230092 590729
PDR ADOCK 04003453
C PDR