

50-346



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001

May 15, 1997

Mr. John K. Wood
Vice President - Nuclear, Davis-Besse
Centerior Service Company
c/o Toledo Edison Company
Davis-Besse Nuclear Power Station
5501 North State Route 2
Oak Harbor, OH 43449-9760

SUBJECT: DAVIS-BESSE NUCLEAR POWER STATION, UNIT NO. 1 - COMPLETION OF
LICENSING ACTION FOR GENERIC LETTER 95-03, "CIRCUMFERENTIAL CRACKING
OF STEAM GENERATOR TUBES," DATED APRIL 28, 1995 (TAC NO. M92238)

Dear Mr. Wood:

On April 28, 1995, the U.S. Nuclear Regulatory Commission (NRC) issued Generic Letter (GL) 95-03, "Circumferential Cracking of Steam Generator Tubes," to all holders of operating licenses or construction permits for pressurized-water reactors. The NRC issued GL 95-03 for three principal reasons:

- (1) Notify addressees about the safety significance of the recent steam generator tube inspection findings at Maine Yankee Atomic Power Station;
- (2) Request that all addressees implement the actions described within the generic letter; and
- (3) Require that all addressees submit to the NRC a written response regarding implementation of the requested actions.

In addition, GL 95-03 alerted addressees to the importance of performing comprehensive examinations of steam generator tubes using techniques and equipment capable of reliably detecting the types of degradation to which the steam generator tubes may be susceptible. The staff also noted that the performance of steam generator tube examinations is controlled, in part, by Appendix B to Title 10, Part 50, of the *Code of Federal Regulations* (10 CFR Part 50).

In GL 95-03, the NRC staff also requested that licensees take the following actions:

- (1) Evaluate recent operating experience with respect to the detection and sizing of circumferential indications to determine the applicability to their plants;
- (2) On the basis of the evaluation in Item (1) above, as well as past inspection scope and results, susceptibility to circumferential cracking, threshold of detection, expected or inferred crack growth rates, and other relevant factors, develop a safety assessment justifying continued operation until the next scheduled steam generator tube inspections; and

9705210134 970515
PDR ADOCK 05000346
P PDR

dfol
1/0

- (3) Develop plans for the next steam generator tube inspections as they pertain to the detection of circumferential cracking. The inspection plans should address, but not be limited to, scope (including sample expansion criteria, if applicable), methods, equipment, and criteria (including personnel training and qualification).

To document the outcome of these actions, the NRC staff requested that addressees prepare and submit the following:

- (1) A safety assessment justifying continued operation, predicated on the evaluation performed in accordance with requested Actions 1 and 2 above; and
- (2) A summary of the inspection plans developed in accordance with requested Action 3 above, and a schedule for the next planned inspection.

In response to GL 95-03, you provided letters dated June 23, 1995, February 1, 1996, and June 3, 1996, for Davis-Besse. These submittals provided the information requested by GL 95-03. Therefore, TAC No. M92238 is closed. For your information, the staff's findings regarding this issue are contained in NUREG-1604, "Circumferential Cracking of Steam Generator Tubes."

If you have any questions regarding this matter, please contact me at (301) 415-1390.

Sincerely,

Original signed by:

Allen G. Hansen, Project Manager
Project Directorate III-3
Division of Reactor Projects III/IV
Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page

DISTRIBUTION:

Docket File
PD3-3 R/F
PUBLIC
KKarwoski, EMCB

JRoe
EAdensam (EGA1)
GMarcus
SDembek, SPO-L

OGC
ACRS
GGrant, RIII

DOCUMENT NAME: G:\DAVISBES\DB92238.LTR

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

OFFICE	LA:PD3-3	C	PM:PD3-3	C					
NAME	CBoyle		AHansen						
DATE	05/15/97		05/15/97						

OFFICIAL RECORD COPY

- (3) Develop plans for the next steam generator tube inspections as they pertain to the detection of circumferential cracking. The inspection plans should address, but not be limited to, scope (including sample expansion criteria, if applicable), methods, equipment, and criteria (including personnel training and qualification).

To document the outcome of these actions, the NRC staff requested that addressees prepare and submit the following:

- (1) A safety assessment justifying continued operation, predicated on the evaluation performed in accordance with requested Actions 1 and 2 above; and
- (2) A summary of the inspection plans developed in accordance with requested Action 3 above, and a schedule for the next planned inspection.

In response to GL 95-03, you provided letters dated June 23, 1995, February 1, 1996, and June 3, 1996, for Davis-Besse. These submittals provided the information requested by GL 95-03. Therefore, TAC No. M92238 is closed. For your information, the staff's findings regarding this issue are contained in NUREG-1604, "Circumferential Cracking of Steam Generator Tubes."

If you have any questions regarding this matter, please contact me at (301) 415-1390.

Sincerely,

Original signed by:

Allen G. Hansen, Project Manager
Project Directorate III-3
Division of Reactor Projects III/IV
Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page

DISTRIBUTION:

Docket File
PD3-3 R/F
PUBLIC
KKarwoski, EMCB

JRoe
EAdensam (EGA1)
GMarcus
SDembek, SPO-L

OGC
ACRS
GGrant, RIII

DOCUMENT NAME: G:\DAVISBES\DB92238.LTR

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

OFFICE	LA:PD3-3	C	PM:PD3-3	C					
NAME	CBoyle		AHansen						
DATE	05/15/97		05/15/97						

OFFICIAL RECORD COPY

John K. Wood
Toledo Edison Company

cc:

Mary E. O'Reilly
Centerior Energy Corporation
300 Madison Avenue
Toledo, Ohio 43652

James L. Freels
Manager - Regulatory Affairs
Toledo Edison Company
Davis-Besse Nuclear Power Station
5501 North State - Route 2
Oak Harbor, Ohio 43449-9760

Gerald Charnoff, Esq.
Shaw, Pittman, Potts
and Trowbridge
2300 N Street, N.W.
Washington, D.C. 20037

Regional Administrator
U.S. NRC, Region III
801 Warrenville Road
Lisle, Illinois 60523-4351

Robert B. Borsum
Babcock & Wilcox
Nuclear Power Generation Division
1700 Rockville Pike, Suite 525
Rockville, Maryland 20852

Resident Inspector
U. S. Nuclear Regulatory Commission
5503 North State Route 2
Oak Harbor, Ohio 43449

James H. Lash, Plant Manager
Toledo Edison Company
Davis-Besse Nuclear Power Station
5501 North State Route 2
Oak Harbor, Ohio 43449-9760

Donna Owens, Director
Ohio Department of Commerce
Division of Industrial Compliance
Bureau of Operations and Maintenance
6606 Tussing Road
P.O. Box 4009
Reynoldsburg, Ohio 43068-9009

Davis-Besse Nuclear Power Station
Unit No. 1

Robert E. Owen, Chief
Bureau of Radiological Health
Service
Ohio Department of Health
P. O. Box 118
Columbus, Ohio 43266-0118

James R. Williams
Chief of Staff
Ohio Emergency Management Agency
2855 West Dublin Granville Road
Columbus, Ohio 43235-2206

Roy P. Lessy, Jr., Esq.
Andrew G. Berg, Esq.
Akin, Gump, Strauss, Hauer
& Feld, L.L.P.
1333 New Hampshire Ave., NW, Ste. 400
Washington, D.C. 20036

Ohio Environmental Protection Agency
DERR--Compliance Unit
ATTN: Zack A. Clayton
P. O. Box 1049
Columbus, Ohio 43266-0149

State of Ohio
Public Utilities Commission
180 East Broad Street
Columbus, Ohio 43266-0573

Attorney General
Department of Attorney
30 East Broad Street
Columbus, Ohio 43216

President, Board of County
Commissioner of Ottawa County
Port Clinton, Ohio 43252