

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 6 | The setpoint of temperature switch 2B21-NO10C, a fenwal switch, had drifted from

1 1 | 200°F. to 217°F. The switch was recalibrated per HNP-2-5234.

1 2 |

1 3 |

1 4 |

7 8 9

FACILITY STATUS		N POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
1	5	B	28	0	0	0	29	NA	Z	31	NA	32
7	6	9		10		12	13		45	46		47

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 Z 34

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

44

LOCATION OF RELEASE (36)

NA

45 46

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	2		0	0	0	17	Z	38	NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	30 NA

6 9 10 PUBLICITY (45)
ISSUED DESCRIPTION (44) NRC USE ONLY

NRC USE ONLY

7810170343

R. T. Nix

Superintendent of Maintenance

PHONE: (912) 367-7781