

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 G A E I H 2 2 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

CON'T
01 REPORT SOURCE L 6 0 5 0 0 0 3 6 6 7 0 9 2 3 7 8 8 1 1 0 0 6 7 9 9
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With the Reactor in the Run mode, the CRD hatch cover was removed. While the CRD
03 hatch was open, both personnel airlock doors were opened. The leak rate tests to
04 prove containment integrity, after the hatch and doors were secured, had not been
05 completed in the specified time of one hour. HNP-2-1020 was initiated for normal
06 reactor shutdown per Technical Specifications 3.6.1.1.
07
08

09
7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

SYSTEM CODE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
CAUSE CODE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
CAUSE SURCODE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
COMP. SUBCODE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
VALVE SUBCODE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

17 LER/RO REPORT NUMBER 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
EVENT YEAR 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
SEQUENTIAL REPORT NO. 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
OCCURRENCE CODE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
REPORT TYPE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
REVISION NO. 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

ACTION TAKEN 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
FUTURE ACTION 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
EFFECT ON PLANT 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
SHUTDOWN METHOD 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
HOURS 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
ATTACHMENT SUBMITTED 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
NPRD-4 FORM SUB. 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
PRIME COMP. SUPPLIER 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
COMPONENT MANUFACTURER 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The CRD hatch cover was removed because the inner personnel airlock door had jammed.
11 The outer airlock door was opened while the inner door was being repaired. The CRD
12 hatch and airlock doors were secured and a leak rate test run on both. The leak rate
13 tests were acceptable and HNP-2-1020 was discontinued.
14

15 FACILITY STATUS 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
% POWER 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
OTHER STATUS 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
METHOD OF DISCOVERY 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
DISCOVERY DESCRIPTION 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

16 ACTIVITY CONTENT 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
RELEASED OF RELEASE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
AMOUNT OF ACTIVITY 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
LOCATION OF RELEASE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

17 PERSONNEL EXPOSURES 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
NUMBER 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
TYPE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
DESCRIPTION 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

18 PERSONNEL INJURIES 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
NUMBER 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
DESCRIPTION 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

19 LOSS OF OR DAMAGE TO FACILITY 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
TYPE 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
DESCRIPTION 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

20 PUBLICITY 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
ISSUED 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
DESCRIPTION 7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

NRC USE ONLY

NAME OF PREPARER R. T. Nix
Superintendent of Maintenance

PHONE: (912) 367-7781

7810180003

950 91 7-926