

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No. 030-06061/78-01

Docket No. 030-06061

License No. 37-02375-08 Priority VII Category K

Licensee: U. S. Steel Corporation

Irvin Works

Dravesburg, Pennsylvania

Facility Name: _____

Inspection at:

Inspection conducted:

Inspectors: Benny O'Neill

B. O'Neill, Radiation Specialist

11/24/78
date signed

date signed

date signed

Approved by: R. O. McClintock

R. O. McClintock, Chief, Materials Radiological
Protection Section

11/24/78
date signed

Inspection Summary:

Telephone inquiry conducted October 11, 1978

Areas Covered: Expiration of License, Application for New License

Results: An application for a new license has been filed. No further action is planned.

7812260158

DETAILS

1. Person Contacted

Mr. E. Ward

2. Expiration of License

The inspector telephoned the licensee on October 11, 1978, and notified him that U. S. Steel Corporation License 37-02375-08 had expired on June 30, 1978. The licensee informed the inspector that they still possessed the byproduct material and wished to maintain this license. A letter, together with an NRC-313 application form, was sent to the licensee informing him that this possession constituted noncompliance with 10 CFR 30.3.

3. Application for New License

On November 13, 1978, the Regional Office received a copy of the letter forwarding an application for a new license, together with the enclosed license fee, to the Radioisotopes Licensing Branch.

4. Evaluation by the Regional Office

Region I has evaluated the information supplied by the licensee, and since an application has been filed for the material involved, determined that no further action is required by this office.