



Log # TXX 88271
File # 10110
908.3
Ref. # 10CFR50.55(e)

March 1, 1988

William G. Counsil
Executive Vice President

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION
DOCKET NOS. 50-445 AND 50-446
CABLE TRAY TEE FITTINGS
SDAR: CP-85-50 (SUPPLEMENTAL REPORT)

Gentlemen:

On December 6, 1985, we verbally notified your Mr. H. S. Phillips of a deficiency involving the use of improper welding processes in the manufacturing of cable tray tee fittings, which we determined to be reportable under 10CFR50.55(e) in our last report logged TXX-6771 dated September 30, 1987.

In our last report we stated that we would complete the repair of the deficient tees for both units by March 1, 1988. Due to scheduling constraints, however, we have had to reschedule this activity to June 14, 1988 for Unit 1. Unit 2 tee fitting repair will be completed prior to Unit 2 fuel load.

Very truly yours,

W. G. Counsil

W. G. Counsil

By: J. S. Marshall
J. S. Marshall
Supervisor, Generic Licensing

RSB/clk

c-Mr. R. D. Martin, Region IV
Resident Inspectors, CPSEJ (3)

8803020209 880301
PDR ADOCK 05000445
S DCD

IE27
1/0