

TELECOPY MESSAGE

CD 1/10

Pm 12:30

TO: Mr. G. T. Berry FROM: J. D. Leonard DATE/TIME: December 18, 1978
 Mr. J. F. Davis
 Mr. P. H. Lyon

TO: Mr. Royce H. Grier
 Director of Regulatory Operation
 USNRC Region I
 631 Park Avenue
 King of Prussia, PA. 19406

SUBJECT: PROMPT REPORTABLE OCCURRENCE
 DOCKET NO. 50-333 LICENSE NO. DFR-33
 ASSIGNED OR NO. 78-151
 LER NO. 78-007/01X-0

SENT DATE: December 15, 1978

REPORT DATE: December 18, 1978

EVENT DESCRIPTION: During scheduled December performance of surveillance on the temperature switches associated with detection of FPC1 Turbine/Stator Line area high temperature, it was discovered that the instruments had been set above the limit specified by Technical Specification Table 3.2-2 during the November, 1978 surveillance. During November the switches were erroneously set approximately 76° above maximum ambient temperature instead of the specified $\leq 10^{\circ}$.

INSTRUMENTS INVOLVED:

23-TS-94A, 23-TS-94B, 23-TS-117A, 23-TS-117B, 13-TS-107C, 13-TS-107D, 13-TS-107E and 13-TS-107F (Ambient Temperature Switches)

CAUSE AND REMEDIAL ACTION:

Personnel used the wrong conversion table during the November surveillance. A caution will be placed in the surveillance procedure to clearly indicate the proper table. This should preclude recurrence.

QUALITY STATUS:

2 THERMAL 84 69%

a) Routine Startup _____
 b) Routine Shutdown _____
 c) Steady State Power _____
 f) Load Change X _____

g) Shutdown _____
 h) Refueling _____
 i) Other _____
 j) Not Applicable _____

Written follow-up report will be sent within two weeks.

TELECOPIED

TO: Mr. G. T. Berry

FROM: J. D. Leonard - JAF

DATE: 12-18-78

TIME: _____

NUMBER: 8-15-1

J. D. Leonard, Jr.
 Resident Manager

781226 0189

APR 2 5/10