



Log # TXX 88270  
File # 10110  
# 903.10  
Ref. # 10CFR50.55(e)

March 1, 1988 - 24

William G. Council  
Executive Vice President

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION  
DOCKET NOS. 50-445 AND 50-446  
EQUIPMENT CONDUIT INTERFACE  
SDAR: CP-85-39 (SUPPLEMENTAL REPORT)

Gentlemen:

On January 11, 1988, we notified you via our report logged TXX-88035 of a reportable deficiency involving conduit which was not installed in accordance with design documents. The purpose of this letter is to provide estimated completion dates for the remaining two corrective action items required to resolve the conduit-to-equipment interfaces outside of the vendor approved entry area. Our last report was logged TXX-88214 dated February 22, 1988.

Specifically, in report logged TXX-88035 dated January 11, 1988, three corrective action items were specified to correct the deficient conduit-to-equipment interface condition. As stated in our last report, logged TXX-88214, Specification 2323-ES-100 has been modified to correct the deficient condition in the specification.

Unit 1 repair/rework of the affected cabinets and correction of the equipment qualification documents will be completed by May 15, 1988.

The required Unit 2 corrective action will be completed prior to Unit 2 fuel load.

Very truly yours,

W.G. Council

W. G. Council

By: J. S. Marshall  
J. S. Marshall  
Supervisor, Generic Licensing

RSB/clk

c-Mr. R. D. Martin, Region IV  
Resident Inspectors CPSES (3)

8803080242 880301  
PDR ADOCK 05000445  
S DCD

IE 27  
1/0