

bcc:

JAN 10 1973

Docket No. 50-29

Docket File  
RP Reading  
Branch REading  
AEC PDR  
DJSkovholt  
ACRS (16)  
RO (3)  
OGC  
RJSchemel  
TJCarter  
ABurger  
SATEets  
RRMaccary  
RDDuncan

Yankee Atomic Electric Company  
ATTN: Louis H. Heider  
20 Turnpike Road  
Westboro, Massachusetts 01581

Gentlemen:

Your letter dated December 1, 1972, provided additional information on two outstanding items relating to Yankee's report on the "March, 1972 Inservice Examination of Yankee- Rowe Atomic Power Plant".

Based on our review of this information that you submitted in response to our letter dated November 17, 1972, we have concluded:

1. The correction of the code rejectable area in the 2-inch charging line weld (CH-5) as described by you is acceptable, and
2. Since no evidence of a change in the condition of the pressurizer cladding was found during the November 1970 inservice inspection, your proposed schedule to examine the pressurizer cladding during every third refueling outage provides for tripling of the inspection frequency required by Section XI of the ASME Boiler and Pressure Vessel Code, and is acceptable.

Sincerely,

151

Donald J. Skovholt  
Assistant Director  
for Operating Reactors  
Directorate of Licensing

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES

OFFICE ▶	L:OR	L:OR	L:OR	LRS	L:OR	
SURNAME ▶	ABurger:rw	SATEets	RJSchemel	RRMaccary	DJSkovholt	
DATE ▶	1/9/73	1/9/73	1/9/73	1/10/73	1/10/73	

8011050601