



Energy Harbor Nuclear Corp.
Beaver Valley Power Station
P. O. Box 4
Shippingport, PA 15077

John J. Grabnar
Site Vice President, Beaver Valley Nuclear

724-682-5234

February 7, 2022
L-22-015

10 CFR 50.55a(g)

ATTN: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, DC 20555-0001

SUBJECT:
Beaver Valley Power Station, Unit No. 2
Docket No. 50-412, License No. NPF-73
Twenty-Second Refueling Outage Inservice Inspection Summary Report

In accordance with 10 CFR 50.55a, "Codes and standards," and the American Society of Mechanical Engineers Boiler and Pressure Vessel Code (ASME Code) Case N-532-5, "Repair/Replacement Activity Documentation Requirements and Inservice Inspection Summary Report Preparation and Submission, Section XI, Division 1," enclosed please find the inservice inspection owner's activity report for examinations performed prior to and during the twenty-second refueling outage at Beaver Valley Power Station, Unit No. 2 (BVPS-2).

Inservice inspection activities addressed in the report were performed during the first period of the fourth ten-year interval in accordance with Section XI of the ASME Code, 2013 Edition. The inservice inspection term at BVPS-2 covered by this report includes the period from May 7, 2020 to November 13, 2021.

This letter contains no new regulatory commitments. If you have any questions regarding this report, please contact Mr. Phil H. Lashley, Manager – Fleet Licensing, at (330) 696-7208.

Sincerely,

A handwritten signature in black ink, appearing to read "John J. Grabnar", written over a horizontal line.

John J. Grabnar

Beaver Valley Power Station, Unit No. 2

L-22-015

Page 2

Enclosure: Beaver Valley Power Station, Unit No. 2, Twenty-Second Refueling Outage
Inservice Inspection Owner's Activity Report

cc: NRC Region I Administrator
NRC Resident Inspector
NRC Project Manager
Director BRP/DEP
Site BRP/DEP Representative

Enclosure
L-22-015

Beaver Valley Power Station, Unit No. 2
Twenty-Second Refueling Outage Inservice Inspection Owner's Activity Report

(2 pages follow)

FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number BV2-OAR1-2R22

Plant Beaver Valley Power Station

Unit No. 2 Commercial Service Date November 17, 1987 Refueling Outage No. 2R22
(if applicable)

Current Inspection Interval 4th
(1st, 2nd, 3rd, 4th, other)

Current Inspection Period 1st
(1st, 2nd, 3rd)

Edition and Addenda of Section XI applicable to the inspection plan 2013 Edition

Date and Revision of inspection plans 10/11/21, ADM-2039, Rev. 19

Edition and Addenda of Section XI applicable to repair/replacement activities, if different than the inspection plans Same

Code Case Used: N-532-5, N-722-1, N-729-6, N-770-5, N-716-1, and N-513-4
(if applicable, including cases modified by Case N-532 and later revisions)

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting completion of 2R22 conform to the requirements of Section XI.
(refueling outage number)

Signed LPS Date 01/14/22
L. Seaman, ISI Program Engineer

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and employed by Hartford Steam Boiler Inspection and Insurance Company of Hartford, Connecticut have inspected the items described in the

Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

P. Bolbrich Commission NB 15908 NI
Inspector's Signature (National Board Number and Endorsement)

Date 01/14/22

TABLE 1
ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED EVALUATION FOR CONTINUED SERVICE

Examination Category and Item Number	Item Description	Evaluation Description
D-B D2.10	2SWS-024-078	A code case 513-4 evaluation was performed for a through wall flaw. This was later repaired during 2R22 by RRP number 4348 in Table 2. (CR-2021-07205 and CR-2021-07353)

TABLE 2
ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE

Code Class	Item Description	Description of Work	Date Completed (1)	Repair/Replacement Plan Number
3	2-SWS-024-078	Replace section of piping where code case N-513-4 was used for continued service. (CR-2021-07205)	01/05/2022	4348
1	Reactor Head Control Rod Drive Mechanism Nozzle Number 27	Buffing/grinding/welding to remove a surface discontinuity which caused a Liquid Penetrant exam indication in the previously repaired weld overlay surface. (CR-2021-08025)	11/28/2021	4358
1	Reactor Head Control Rod Drive Mechanism Nozzle Number 28	Weld overlay repair applied per approved relief request 2-TYP-4-RV-04 (CR-2021-07969)	11/29/2021	4355
1	Reactor Head Control Rod Drive Mechanism Nozzle Number 40	Weld overlay repair applied per approved relief request 2-TYP-4-RV-04 (CR-2021-07948)	11/29/2021	4353

Notes:

- (1) "Date Completed" is the date that the Repair Replacement Plan final signature was applied. This date may be after the end of the reporting period for work that was physically completed within the reporting period.
- (2) Steam Generator activities are reported under separate correspondence in Technical Specification required reports.