ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9403100183 DOC.DATE: 94/03/02 NOTARIZED: NO DOCKET #
FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
AUTH.NAME AUTHOR AFFILIATION
PARRISH,J.V. Washington Public Power Supply System
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Forwards Rev 1 to LER 93-030.Rev includes addl cable tray deficiencies identified during walkdown of accesible areas. Areas presently inaccessible due to high radiation will be walked down during 1994 refueling outage.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+7
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	PDV PD	1	1	CLIFFORD,J	1	1
INTERNAL:	ACRS	2	2	AEOD/DOA	1	1
	AEOD/DSP/TPAB	1	1	AEOD/ROAB/DSP	2	2
	NRR/DE/EELB	1	1	NRR/DE/EMEB	1	1
	NRR/DORS/OEAB	1	1	NRR/DRCH/HHFB	1	1
	NRR/DRCH/HICB	1	1	NRR/DRCH/HOLB	1	1
	NRR/DRIL/RPEB	1	1	NRR/DRSS/PRPB	2	2
	NRR/DSSA/SPLB	1	1	NRR/DSSA/SRXB	1	1
	REG FILE 02	1	1	RES/DSIR/EIB	1	1
	RGN5 FILE 01	1	1			
EXTERNAL:	EG&G BRYCE,J.H	2	2	L ST LOBBY WARD	1	1
	NRC PDR	1	1	NSIC MURPHY,G.A	1	1
	NSIC POORE,W.	1	1	NUDOCS FULL TXT	1	1

R I D S / A D D S

R I D S / A D D S

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 29 ENCL 29

A04

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352-0968 • (509) 372-5000

March 2, 1994
G02-94-054

Docket No. 50-397

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: **NUCLEAR PLANT WNP-2, OPERATING LICENSE NPF-21**
LICENSEE EVENT REPORT NO. 93-030, REVISION 1

Transmitted herewith is Revision 1 to Licensee Event Report (LER) No. 93-030 for the WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the items of reportability, corrective action taken, and action taken to preclude recurrence.

The original LER reported the discovery of missing electrical power raceway cable tray covers during walkdowns originally undertaken to identify the installation locations of noncredited Thermolag fire barriers. Walkdowns of accessible areas were approximately 50% complete when the LER was issued. This revision includes the additional cable tray deficiencies identified during the walkdown of accessible areas completed on January 25, 1994.

Areas presently inaccessible due to high radiation will be walked down during the 1994 (R-9) Refueling Outage. If necessary, an additional revision to this LER will be submitted thirty days after completion of the R-9 Refueling Outage to report additional similar deficiencies. Any unrelated 10CFR50.73 reportable events or conditions discovered during the walkdown project will be reported separately.

Sincerely,

Gregory O Smith / For
J. V. Parrish (Mail Drop 1023)
Assistant Managing Director, Operations

JVP/BRH/bk
Enclosure
cc: Mr. K. E. Perkins, NRC - Region V
Mr. R. Barr, NRC Resident Inspector (Mail Drop 927N, 2 Copies)
INPO Records Center - Atlanta, GA
Mr. D. L. Williams, BPA (Mail Drop 399)

080083

9403100183 940302
PDR ADOCK 05000397
S PDR

JE22 1