REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8103030831 DOC.DATE: 81/02/27 NOTARIZED: NO DOCKET #
FACIL:50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
AUTH.NAME AUTHOR AFFILIATION
SHALLER,D.V. Indiana & Michigan Power Co.
RECIP.NAME RECIPIENT AFFILIATION
KEPPLER,J.G. Region 3, Chicago, Office of the Director

SUBJECT: Final deficiency rept re possible svc water leak in ventilation unit of lower vol containment,initially reported 810220.Drip pan pipe had become plugged.Drip pan overflowed. No leak exists.Requests notification withdrawal.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1
TITLE: Incident Reports

NOTES:Send 3 copies of all material to I&E. 05000316

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
ACTION:	VARGA,S. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACTO09	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1	1
	AEOD	3	3	ASLBP/J.HARD	1	1
	AUX SYS BR 15	1	1	CHEM ENG BR 16	1	1
	CONT SYS BR 17	1	1	CORE PERF BR 18	1	1
	DIR,DIV OF LIC	1	1	DIR,ENGINEERI20	1	1
	DIR,HUM FAC S21	1	1	DIR,SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	2	2	JORDAN,E./IE	1	1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	MPA	3	3
	NRC PDR 02	1	1	OP EX EVAL BR34	3	3
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	REG FILE 01	1	1	REL & RISK A 41	1	1
	SFTY PROG EVA42	1	1	STRUCT ENG BR44	1	1
	SYS INTERAC B45	1	1			
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	1
	NSIC 05	1	1	TERA:DOUG. MAY	1	1

MAR 04 1981

TOTAL NUMBER OF COPIES REQUIRED: LTTR 68 ENCL ~~68~~ 71 0

RB

DISTRIBUTION SERVICES UNIT
1981 MAR 3 AM 9 30
US NRC DISTRIBUTION SERVICES BRANCH

American Electric Power System
INDIANA & MICHIGAN POWER COMPANY
DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

February 27, 1981

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

This is a follow up to our letter of February 20, 1981 concerning a possible service water leak in a ventilation unit of the lower volume of Unit 2 Containment.

The investigation revealed that the water was not from a service water leak, but from the normal condensation which occurs as the Containment Atmosphere passes over the cooling coils. The drip pan drain had become plugged causing the drip pan to overflow and run into the Pipe Tunnel Sump.

Therefore, in as much as no service water leak exists we are requesting that the notification be withdrawn.

Sincerely,

D. V. Shaller
Plant Manager

/pd

A002
S
1/0

cc: J. E. Dolan
R. S. Hunter
R. W. Jurgensen
R. F. Kroeger
R. W. Kilburn
E. Swanson/N. DuBry Resident Inspectors
R. C. Callen MPSC
G. Charnoff, Esq.
J. M. Hennigan
W. Lavallee EPRI
PNSRC
J. F. Stietzel
E. L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

S

8103030831