CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9901260344 DOC.DATE: 99/01/18 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH.NAME AUTHOR AFFILIATION
SAMPSON,J.R. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
RECIP.NAME RECIPIENT AFFILIATION
Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-052-01,re potential failure mode for air operated components not considered in original design. Interim LER has been updated to include two addl instances of same failure mode.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 14
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	PD3-3 PD	1	1	STANG,J	1	1
INTERNAL:	AEOD/SPD/RAB	2	2	AEOD/SPD/RRAB	1	1
	FILE CENTER	1	1	NRR/DE/ECGB	1	1
	NRR/DE/EELB	1	1	NRR/DE/EMEB	1	1
	NRR/DRCH/HICB	1	1	NRR/DRCH/HOHB	1	1
	NRR/DRCH/HQMB	1	1	NRR/DRPM/PECB	1	1
	NRR/DSSA/SPLB	1	1	RES/DET/EIB	1	1
	RGN3 FILE 01	1	1			
EXTERNAL:	L ST LOBBY WARD	1	1	LITCO BRYCE,J H	1	1
	NOAC POORE,W.	1	1	NOAC QUEENER,DS	1	1
	NRC PDR	1	1	NUDOCS FULL TXT	1	1

C A T E G O R Y 1 D O C U M E N T

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 22

RO

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901

AEP
INDIANA
MICHIGAN
POWER

January 18, 1999

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following interim report is being submitted:

LER 315/98-052-01, Potential Failure Mode for Air Operated Components Not Considered in Original Design".

This interim LER has been updated to include two additional instances of the same failure mode. As a result, the title of the LER has been changed to reflect that the potential failure mode is not confined to the Auxiliary Feedwater System. The change to the title and all changes to the text have been marked with sidebars.

Sincerely,

John R. Sampson

J. R. Sampson
Site Vice President

/mbd
Attachment

c: J. L. Caldwell (Acting), Region III
R. P. Powers
P. A. Barrett
J. B. Kingseed
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector

1/1

IE22

9901260344 990118
PDR ADOCK 05000315
S PDR

Printed on recycled paper