NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | VASPS2 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T
01 | REPORT SOURCE L (6) | 05000281 (7) | 081580 (8) | 091280 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While reviewing Unit 2 pipe support work it was discovered that a seismic support for
03 charging pump 2-CH-P-1B had not been installed. This was contrary to the order that
04 such would be accomplished prior to commencing power operation. Two charging pumps
05 were at all times operable as specified in Technical Specification 3.3.A.5 providing
06 the required protection for the health and safety of the public.
07
08

09 SYSTEM CODE RB (11) | CAUSE CODE B (12) | CAUSE SUBCODE C (13) | COMPONENT CODE SUPORT (14) | COMP. SUBCODE B (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 80 | — | SEQUENTIAL REPORT NO. 012 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN F (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER X999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 In the administration of the paperwork involving the myraid repairs and replacements,
11 the installation of this support was inadvertantly neglected. Once noted, immediate
12 action was taken and the missing support was installed.
13
14

15 FACILITY STATUS B (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY D (31) | DISCOVERY DESCRIPTION (32) Vendor Review Of Work

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

8009220 309

NAME OF PREPARER J. L. Wilson PHONE: (804) 357-3184

GPO 917-926

ATTACHMENT 1 (PAGE 1 OF 1)
SURRY POWER STATION, UNIT NO. 2
DOCKET NO: 50-281
REPORT NO: 80-012/03L-0
EVENT DATE: 08-15-80

TITLE OF EVENT: MISSING PIPE SUPPORT

1. DESCRIPTION OF EVENT:

With the unit critical at 0% power, a review of the paperwork surrounding the installation and modification of the pipe supports revealed that one support on charging pump 2-CH-P-1B was missing. This is contrary to the order permitting resumption of operations.

2. PROBABLE CONSEQUENCES:

Two remaining charging pumps were operable fulfilling the obligations cited in Technical Specification 3.3.A.5 and assuring the health and safety of the public were not jeopardized.

3. CAUSE:

While reviewing the voluminous paperwork accompanying the pipe support work, it was discovered that a typographical error had been made in determining which supports were required to be installed prior to operation of the unit.

4. IMMEDIATE CORRECTIVE ACTION:

The charging pump involved was removed from service.

5. SUBSEQUENT CORRECTIVE ACTION:

The missing support was installed.

6. FUTURE CORRECTIVE ACTION:

None

7. GENERIC IMPLICATIONS:

None