NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N C B E P 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T

01 | REPORT SOURCE L (6) | 0 5 0 - 0 3 2 5 (7) | 0 9 0 5 7 9 (8) | 1 0 0 2 7 9 (9)

DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a routine surveillance of the control panel, the operator noticed that he did

03 not have any indication of the valve position for E41-F006, HPCI injection valve, on

04 the RTGB or at the local motor control center. The HPCI system was declared inoper-

05 able.

06 Technical Specifications 3.5.1, 6.9.1.9b

07

08

09 | SYSTEM CODE S F (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE R E L A Y X (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR 7 9 | — | SEQUENTIAL REPORT NO. 0 3 8 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER G 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The control power fuse was found blown due to a shorted relay coil. The fuse and

11 the relay coil were replaced. A reason could not be determined for the shorted coil.

12 As this is a first time occurence, this is considered an isolated event and no further

13 action is required.

14

15 | FACILITY STATUS E (28) | % POWER 0 5 4 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) NA

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES

17 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES

18 | NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY

19 | TYPE Z (42) | DESCRIPTION NA

PUBLICITY

20 | ISSUED N (44) | DESCRIPTION (45) NA

NRC USE ONLY

1134 145

7910010 286

NAME OF PREPARER A. C. Tollison, Jr. PHONE: 919-457-9521

GPO 917-926