NRC FORM 366 (7 77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

UPDATE REPORT - PREVIOUS REPORT DATE 11-30-78

CONTROL BLOCK: (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 LICENSEE CODE: N C B E P 2 (2) LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) LICENSE TYPE: 4 1 1 1 1 (4) CAT (5)

CON'T 01 REPORT SOURCE: L (6) DOCKET NUMBER: 0 5 0 - 0 3 2 4 (7) EVENT DATE: 1 1 0 1 7 8 (8) REPORT DATE: 0 3 2 1 7 9 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the rod block monitor (RBM) periodic test (P.T. 1.5PC), RBM Channel A was

03 found out of calibration. (Technical Specification 3.1.4.3).

04

05

06

07

08

09 SYSTEM CODE: R B (11) CAUSE CODE: X (12) CAUSE SUBCODE: Z (13) COMPONENT CODE: I N S T R U (14) COMP. SUBCODE: X (15) VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR: 7 8 — SEQUENTIAL REPORT NO.: 0 7 2 / OCCURRENCE CODE: 0 3 REPORT TYPE: X — REVISION NO.: 1

ACTION TAKEN: E (18) FUTURE ACTION: X (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS (22): 0 0 0 0 ATTACHMENT SUBMITTED: N (23) NPRD-4 FORM SUB.: Y (24) PRIME COMP. SUPPLIER: N (25) COMPONENT MANUFACTURER: G 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The RBM was out of calibration due to setpoint drift. The monitor was recalibrated

11 and returned to service. Frequency of calibration for the monitor will be increased

12 from once per year to twice per year. This action should prevent similar events from

13 occuring.

14

15 FACILITY STATUS: E (28) % POWER: 0 9 9 (29) OTHER STATUS (30): NA METHOD OF DISCOVERY: B (31) DISCOVERY DESCRIPTION (32): Periodic Test

16 ACTIVITY RELEASED: Z (33) CONTENT OF RELEASE: Z (34) AMOUNT OF ACTIVITY (35): NA LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES

17 NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION (39): NA

PERSONNEL INJURIES

18 NUMBER: 0 0 0 (40) DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43)

19 TYPE: Z (42) DESCRIPTION: NA

7903270532

PUBLICITY ISSUED DESCRIPTION (45)

NRC USE ONLY