NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJSGS1 (2) | 00-000000-00 (3) | 4 | 1111 (4) | (5)
LICENSEE CODE (7–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26) | CAT (57–58)

CON'T
01 | REPORT SOURCE L (6) | 05000272 (7) | 021081 (8) | 090382 (9)
DOCKET NUMBER (60–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During an inspection of the Spent Fuel Pit, a leak of approximately 2.7 liters/hour
03 was discovered at telltale drain number 6. The Spent Fuel Pit level has been
04 maintained at 23 feet of water over the top of the irradiated fuel assemblies
05 seated in the storage racks in accordance with Technical Specification 3.9.11.
06 Previous similar occurrence: 80-09.
07
08

09 | SYSTEM CODE FB (11) | CAUSE CODE E (12) | CAUSE SUBCODE C (13) | COMPONENT CODE XXXXXX (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 81 | — | SEQUENTIAL REPORT NO. 034 | / | OCCURRENCE CODE 03 | REPORT TYPE X | — | REVISION NO. 1

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER X (25) | COMPONENT MANUFACTURER U080 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The apparent cause was leaking welded seams. A stainless steel plate was welded
11 over a defect in the side wall and epoxy was used to seal three defects in floor
12 seams. A Design Change Package was then implemented which had the tank ultra-
13 sonically tested. The problem areas were identified and welded in accordance
14 with approved procedures.

15 | FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES
17 | NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES
18 | NUMBER 000 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY (43)
19 | TYPE Z (42) | DESCRIPTION N/A

8209160515 820903
PDR ADOCK 05000272
S PDR

PUBLICITY
20 | ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER R. Heller PHONE: (609) 541-5900 629

GPO 917-926