0771

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N J S G S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 1 (7) | 0 4 1 7 8 2 (8) | 0 5 0 5 8 2 (9)

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On two different occassions, during surveillance testing, the 100' Elevation Air

0 3 | Lock inner door seal pressure failed to meet the required pressure of 47 PSIG. In

0 4 | both cases, the air lock was declared inoperable, and Action Statement 3.6.1.3.2 was

0 5 | entered. These occurrences constituted operation in a degraded mode in accordance

0 6 | with Technical Specification 6.9.1.9.b.

0 7 | (82-021, 81-122, 81-112, 81-012)

0 8 | 80

7 8 9

0 9 | SYSTEM CODE S A (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE P E N E T R (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)

7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 2 3 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER C 3 1 0 (26)

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | In the first instance, the inner door low seal pressure was due to a plugged seal

1 1 | air pressurization line. The line was blown out, and the seal was satisfactorily

1 2 | tested. The low seal pressure, on the second occasion resulted from leaky inner

1 3 | door seals. The seals were replaced, and the air lock was satisfactorily tested.

1 4 | In both cases, Action Statement 3.6.1.3.2 was terminated, within the time specified.

7 8 9 80

1 5 | FACILITY STATUS C (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Testing

7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES

1 7 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

7 8 9 11 12 13 80

PERSONNEL INJURIES

1 8 | NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY (43)

1 9 | TYPE Z (42) | DESCRIPTION NA

7 8 9 10 80

8205180 626

PUBLICITY

2 0 | ISSUED N (44) | DESCRIPTION (45) NA

7 8 9 10 68 69 80

NRC USE ONLY

NAME OF PREPARER R. Frahm PHONE (609) 541-5900 629

NRC 017-926