NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N C M G S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 9 (7) | 0 3 0 4 8 2 (8) | 0 4 0 1 8 2 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in mode 5, an operator (in training) attempting to address the status of a
03 fire zone through the Honeywell Fire Detection System Operator Terminal (OPT)
04 mistakenly dumped the Central Processing Unit (CPU) memory, resulting in the
05 Fire Detection System being declared inoperable since the system would not pro-
06 vide control room alarms. This violates T.S.3.3.3.7 which is reportable per
07 T.S.6.9.1.13(b). Since fire watches were immediately established and no actual
08 fire conditions were discovered, the health and safety of the public were unaffected.

09 | SYSTEM CODE A B (11) | CAUSE CODE A (12) | CAUSE SUBCODE B (13) | COMPONENT CODE Z Z Z Z Z Z (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 2 0 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Access to the CPU memory is limited to system maintenance purposes. The operator
11 did not understand the limits of his responsibilities concerning the Fire Detec-
12 tion System, and inadequate warning (a note in the key log) existed concerning
13 use of the CPU memory access enable key. The CPU memory was restored and pro-
14 cessor operation verified. Appropriate training will be given, and a warning will
be posted on the OPT panel concerning access to the CPU memory.

15 | FACILITY STATUS X (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) Mode 5 | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Personnel observation

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES
17 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES
18 | NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY (43)
19 | TYPE Z (42) | DESCRIPTION N/A

PUBLICITY
20 | ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

8204160554 820401
PDR ADOCK 05000369
S PDR

NAME: Donald B. Nardoci PHONE: (704) 373-7432