NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJSGS1 (2) | 00-000000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
01 | REPORT SOURCE L (6) | 05000272 (7) | 112481 (8) | 041082 (9)
DOCKET NUMBER (61–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On three separate occasions, November 24 and 28, and December 8, 1982, during the
03 performance of surveillance procedure SP(O) 4.6.1.3, the 100' Elevation Containment
04 Air Lock exceeded the leakage rate limit of 0.05 La at the design pressure of 47.0
05 PSIG as required by Technical Specification 3.6.1.3.b. At 1600, 1935, and 1500 hours,
06 respectively, the air lock was declared inoperable and Action Statement 3.6.1.3 was
07 entered.
08

09 SYSTEM CODE SA (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE PENETR (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 81 | — | SEQUENTIAL REPORT NO. 116 | / | OCCURRENCE CODE 03 | REPORT TYPE X | — | REVISION NO. 1

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER C310 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 On November 24 a seal on the outer door was replaced. On November 28 a seal on the
11 inner door was removed, turned around, and reinstalled. On December 8 the operating
12 handwheel setscrew was reinstalled. On all three occasions surveillance procedures
13 SP(O)4.6.1.3 was satisfactorily performed, and at 1925, 2220, and 2000 hours, respec-
14 tively, Action Statement 3.6.1.3 was terminated. (81-49,81-57,81-89)

FACILITY STATUS E (28) | % POWER 080 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY (31) | DISCOVERY DESCRIPTION (32) Surveillance Test

ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES
NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES
NUMBER 000 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE Z (42) | DESCRIPTION N/A

PUBLICITY
ISSUED N (44) | DESCRIPTION (45) N/A

NRC USE ONLY

8204160609 820401
PDR ADOCK 05000272
S PDR

Dickey PHONE: 609-935-0998

GPO 917-926