NRC FORM 366 (12-81)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

APPROVED BY OMB 3150-0011 EXPIRES 4-30-82

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | S C V C S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 0 0 0 (4) | (5)

LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T

01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 9 5 (7) | 1 2 2 0 8 2 (8) | 0 1 1 9 8 3 (9)

DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On December 20, 1982, with the Plant in Mode 1, Seismic Switch (YM-1782) was

03 | found to have an out-of-tolerance trip point on the Transverse Sensor. The

04 | seismic switch is designed to initiate an alarm upon the recognition of a

05 | seismic event yielding a ground acceleration greater than or equal to the Operating

06 | Base Earthquake. There were no adverse consequences since other seismic instru-

07 | ments at the same location would have properly recorded seismic events and

08 | provided alarms.

09 | SYSTEM CODE I F (11) | CAUSE CODE E (12) | CAUSE SUBCODE G (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE S (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 6 2 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN E (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER (26) K 1 3 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause of this occurrence is attributed to setpoint drift on the Horizontal

11 | Transverse Sensor of Seismic Switch YM-1782. A calibration of the triaxial

12 | seismic switch was performed prior to returning the switch to service on

13 | December 21, 1982. The Licensee plans no additional action other than normal

14 | surveillance testing.

15 | FACILITY STATUS B (28) | % POWER 0 4 8 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operational Test

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A

NRC USE ONLY

8302010120 830119
PDR ADOCK 05000395
S PDR

NAME OF PREPARER C. J. McKinney / C. J. McKinney

PHONE: (803) 345-5209