LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1–6) (PLEASE PRINT ALL REQUIRED INFORMATION)

	LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01	NYNMP1 (7–14)	– – – (15–25)	4 1 1 1 1 (26–30)	0 3 (31–32)

	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01 CONT	- - (57–58)	L (59)	L (60)	0 5 0 – 0 2 2 0 (61–68)	0 3 0 9 7 7 (69–74)	0 4 0 6 7 7 (75–80)

EVENT DESCRIPTION

02 During routine surveillance found reset switch contacts in position which would have
03 prevented three out of six solenoid operated pressure relief valves from operating as
04 required for automatic depressurization. System was not requried at time of surveillance
05 Redundant system would have caused operation of three remaining valves.
06 LER 77-06

	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07	C C (10)	E (11)	I N S T R U (12–17)	A (43)	X 9 9 9 (44–47)	N (48)

CAUSE DESCRIPTION

08 NA
09
10

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	G (9)	0 0 0 (10–12)	NA (13–44)	B (45)	NA (46–80)

	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12	Z (9)	Z (10)	NA (11–44)	NA (45–80)

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION
13	0 0 0 (8–11)	Z (12)	NA (13–80)

PERSONNEL INJURIES

	NUMBER	DESCRIPTION
14	0 0 0 (8–11)	NA (12–80)

~~XXXXXXX~~ CONSEQUENCES PROBABLE

15 NA

LOSS OR DAMAGE TO FACILITY

	TYPE	DESCRIPTION
16	Z (9)	NA (10–80)

PUBLICITY

17 NA

8304060376 770406
PDR ADOCK 05000220
S PDR

ADDITIONAL FACTORS

18 NA

19