LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(2) LICENSEE CODE: A C I H 2 — (3) LICENSE NUMBER: 0 0 0 0 0 0 0 0 0 0 0 — (4) LICENSE TYPE: 4 1 1 1 1 — (5) CAT 58

REPORT SOURCE: L (6) — DOCKET NUMBER: 0 5 0 0 0 3 6 6 (7) — EVENT DATE: 1 2 1 0 7 8 (8) — REPORT DATE: 1 2 2 0 7 8 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

With the reactor in the Run mode, while performing HNP-2-3003 (Reactor Water Level, RPS & PCIS, F.T. & C.), 2B21-N017C was found to trip at 37.7 inches of water decreasing. This fails to comply with Technical Specification Table 3.3.2-2. There were no effects to public health or safe plant operation as 2B21-N017A was operable at the time.

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
C A (11)	X (12)	Z (13)	I N S T R U (14)	S (15)	Z (16)

LER/RO REPORT NUMBER (17)	EVENT YEAR		SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
	7 8	—	0 8 1	0 3	L	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
E (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	N (25)	B 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The cause has been attributed to instrument drift. The instrument was recalibrated per procedure HNP-2-5202 and procedure HNP-2-3003 was completed satisfactorily. 2B21-N017C is a Barton Model 288A switch.

FACILITY STATUS: B (28) — % POWER: 0 5 1 (29) — OTHER STATUS (30): NA — METHOD OF DISCOVERY: B (31) — DISCOVERY DESCRIPTION (32): Surveillance Testing

ACTIVITY RELEASED: Z (33) — CONTENT OF RELEASE: Z (34) — AMOUNT OF ACTIVITY (35): NA — LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES — NUMBER: 0 0 0 (37) — TYPE: Z (38) — DESCRIPTION (39): NA

PERSONNEL INJURIES — NUMBER: 0 0 0 (40) — DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43) — TYPE: Z (42) — DESCRIPTION: NA

PUBLICITY — ISSUED: N (44) — DESCRIPTION (45): NA

7812270273

NRC USE ONLY

NAME OF PREPARER: R. T. Nix — PHONE: (912) 367-7781

Superintendent of Maintenance

GPO 917-026