NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NYIPS2 (2) | 00-00000-00 (3) | 4111 (4) | (5)
7 8 | 9 LICENSEE CODE 14 | 15 LICENSE NUMBER 25 | 26 LICENSE TYPE 30 | 57 CAT 58

CON'T
01 | REPORT SOURCE L (6) | 05000247 (7) | 012079 (8) | 021679 (9)
7 8 | 60 | 61 DOCKET NUMBER 68 | 69 EVENT DATE 74 | 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, the signal from one of two low level alarm
03 devices (LIC-921) for the refueling water storage tank became erratic,
04 making that alarm inoperable. The redundant alarm for the tank level
05 was operable at the time. The inoperable low level alarm was returned
06 to service within the time limits of Technical Specification 3.3.A.2.f.
07
08
7 8 9 80

09 | SYSTEM CODE IB (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE C (15) | VALVE SUBCODE Z (16)
7 8 | 9 10 | 11 | 12 | 13 18 | 19 | 20

(17) LER/RO REPORT NUMBER | EVENT YEAR 79 | — | SEQUENTIAL REPORT NO. 003 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0
21 22 | 23 | 24 26 | 27 | 28 29 | 30 | 31 | 32

ACTION TAKEN X (18) | FUTURE ACTION F (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER B080 (26)
33 | 34 | 35 | 36 | 37 40 | 41 | 42 | 43 | 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A level instrument controller, LIC-921 (Barton Instrument Company,
11 Model 288) became inoperable when the sensing line associated with it
12 had frozen. Temporary heaters were installed to alleviate the conse-
13 quences of the extreme weather conditions. An engineering study has been
14 requested to determine the permanent measures required to prevent recur-
7 8 9 rence. 80

15 | FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Supervisory Alarm
7 8 | 9 | 10 12 | 13 44 | 45 | 46 80

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
7 8 | 9 | 10 | 11 44 | 45 80

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA
7 8 | 9 11 | 12 | 13 80

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA
7 8 | 9 11 | 12 80

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION NA
7 8 | 9 | 10 80

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY
7 8 | 9 | 10 68 | 69 80

7902270376

NAME OF PREPARER John M. Makepeace PHONE: 914-739-8823

GPO 917-926