Tier / Group	Randomly Selected K/A	Reason for Rejection
1/1/RO	295028 EA1.01	Perry does not have Drywell Spray. Randomly selected EA1.02 Drywell ventilation.
2/1 RO	223002 K2	K2 does not contain any Importance Rating ≥ 2.5; randomly selected K3
2/1 RO	300000 K6.04	Perry does not have Service air refusal valves. Randomly selected K6.07 Valves
2/2/RO	290003 K2	K2 does not contain any Importance Rating ≥ 2.5. Randomly selected K1
2/2/RO	290002 K2	K2 does not contain any K/A. Randomly selected A4. A4 does not contain any K/A. Randomly selected A2
3 SRO	2.4.20	Was unable to write a discriminating question for selected K/A. Randomly selected K/A 2.4.32
2/1/SRO	2.4.20	Was unable to write a discriminating question for selected K/A. Randomly selected K/A 2.2.37
2/1/SRO	2.2.44	Was unable to write a discriminating question for selected K/A. Randomly selected K/A 2.1.32
2/1/RO	209001 2.4.8	Selected K/A (generic part) was covered on Audit Exam. Randomly selected K/A K2.01.
2/1/RO	211000 K2.02	Was unable to write an operationally valid discriminating question for selected K/A. Randomly selected K/A K2.01
2/1/RO	215005 K6.05	Selected K/A was on failure of the IRM's on APRM's. Could not write an operationally valid question. Randomly selected K/A 215005 K6.03 (Detectors)