ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8808250028 DOC.DATE: 88/08/12 NOTARIZED: NO DOCKET #
FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
50-362 San Onofre Nuclear Station, Unit 3, Southern Californ 05000362
AUTH.NAME AUTHOR AFFILIATION
MORGAN,H.E. Southern California Edison Co.
RECIP.NAME RECIPIENT AFFILIATION
MARTIN,J.B. Region 5, Ofc of the Director

SUBJECT: Follow-up RO:of Tecgh Spec fire rated assemblies found inoperable during routine surveillances in Jul 1988.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3
TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	PD5 LA	1	1	PD5 PD	1	1
	HICKMAN,D	1	1			
INTERNAL:	ACRS MICHELSON	1	1	ACRS MOELLER	2	2
	ACRS WYLIE	1	1	AEOD/DOA	1	1
	AEOD/DSP/NAS	1	1	AEOD/DSP/ROAB	2	2
	AEOD/DSP/TPAB	1	1	ARM/DCTS/DAB	1	1
	DEDRO	1	1	NRR/DEST/ADS 7E	1	0
	NRR/DEST/CEB 8H	1	1	NRR/DEST/ESB 8D	1	1
	NRR/DEST/ICSB 7	1	1	NRR/DEST/MEB 9H	1	1
	NRR/DEST/MTB 9H	1	1	NRR/DEST/PSB 8D	1	1
	NRR/DEST/RSB 8E	1	1	NRR/DEST/SGB 8D	1	1
	NRR/DLPQ/HFB 10	1	1	NRR/DLPQ/QAB 10	1	1
	NRR/DOEA/EAB 11	1	1	NRR/DREP/RAB 10	1	1
	NRR/DREP/RPB 10	2	2	NRR/DRIS/SIB 9A	1	1
	NUDOCS-ABSTRACT	1	1	REG FILE 02	1	1
	RES TELFORD,J	1	1	RES/DSIR DEPY	1	1
	RES/DSIR/EIB	1	1	RGN5 FILE 01	1	1
EXTERNAL:	EG&G WILLIAMS,S	4	4	FORD BLDG HOY,A	1	1
	H ST LOBBY WARD	1	1	LPDR	1	1
	NRC PDR	1	1	NSIC HARRIS,J	1	1
	NSIC MAYS,G	1	1			

R I D S / A D D S

R I D S / A D D S

TOTAL NUMBER OF COPIES REQUIRED: LTTR 46 ENCL 45

Southern California Edison Company
SAN ONOFRE NUCLEAR GENERATING STATION
P. O. BOX 128
SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN
STATION MANAGER

TELEPHONE
(714) 368-6241

RECEIVED
NRC
REGION V
88 AUG 15 P1:20

August 12, 1988

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket Nos. 50-361 and 50-362
Follow-up Report, Inoperable Fire Doors - July 1988
San Onofre Nuclear Generating Station, Units 2 and 3

Reference: Letter, H. E. Morgan (SCE) to J. B. Martin (NRC), dated July 29, 1988

In accordance with our referenced letter, this submittal provides the follow-up report of Technical Specification fire-rated assemblies (specifically fire doors) found inoperable during routine surveillances in July 1988.

Fire doors found inoperable during the July routine surveillances are identified in the Attachment and include: 18 latching mechanism failures, 9 closure mechanism failures. No doors were found blocked open in July. As each of these deficiencies was identified, compensatory fire watches pursuant to Technical Specification 3.7.9, Action Statement "a", were established and will remain in effect until the door is restored to operable status.

8808250028 880812
PDR ADOCK 05000361
S PDR

IE22
1/1
IE01

This monthly follow-up report and those sent previously provide updated information associated with an ongoing condition initially reported in 1983. The follow-up report covering inoperable fire doors identified in August 1988 will be submitted during September 1988.

If you require any additional information, please so advise.

Sincerely,

H E Morgan

H. E. MORGAN
STATION MANAGER

ERSiacor:fd/jul
Enclosure

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)
U. S. Nuclear Regulatory Commission Document Control Desk

Institute of Nuclear Power Operations (INPO)

ATTACHMENT
SOUTHERN CALIFORNIA EDISON COMPANY
INOPERABLE FIRE DOORS FOR THE MONTH OF JULY 1988
SAN ONOFRE NUCLEAR GENERATING STATION
UNITS 2 AND 3, DOCKET NOS. 50-361 and 50-362

I. Latching Mechanism Failures:

Number of doors inoperable - 18, as follows:

Door Number	Inoperable	Operable
S3-018	04/12/88	- - -
AC-223	05/04/88	- - -
AR-112	06/11/88	07/11/88
S3-017	06/14/88	07/20/88
AC-328	06/15/88	07/13/88
AC-310	06/17/88	07/14/88
FH3-404	06/24/88	07/15/88
DG3-206	06/26/88	07/01/88
AC-442	06/26/88	07/18/88
AR-404	06/28/88	07/12/88
AR-305	07/02/88	07/09/88
AR-301	07/02/88	07/13/88
S2-018	07/12/88	- - -
AC-338	07/20/88	- - -
AC-349	07/22/88	- - -
AC-417	07/25/88	- - -
AC-127	07/26/88	- - -
S3-017	07/31/88	- - -

II. Closure Mechanism Failures:

Number of doors inoperable - 9, as follows:

Door Number	Inoperable	Operable
AR-502	05/24/88	07/05/88
S3-018	06/08/88	- - -
AC-344	06/23/88	07/19/88
FH3-404	06/24/88	07/08/88
FH2-404	06/24/88	- - -
AR-404	06/28/88	07/12/88
AC-442	07/14/88	07/18/88
AC-236	07/16/88	- - -
AC-349	07/22/88	- - -

III. Doors Blocked Open:

Number of doors blocked open - None